ANNUAL REPORT

OF THE

ARCHÆOLOGICAL DEPARTMENT

SOUTHERN CIRCLE, MADRAS

FOR THE YEAR

(maaaaa)

1915-1916



MADRAS
PRINTED BY THE SUPERINTENDENT, GOVERNMENT PRESS

ANNUAL REPORT

OF THE

ARCHÆOLOGICAL DEPARTMENT

SOUTHERN CIRCLE, MADRAS

FOR THE YEAR

1915-1916



MADRAS
PRINTED BY THE SUPERINTENDENT, GOVERNMENT PRESS

TABLE OF CONTENTS

Part I

										PAGE
Work at head-quarte	rs—									
Preparation of d	lrawings	• •		• •	• •			• •		1
Photography					• •	• •	• •	• •	• •	1
Publications	,.	• •		• •	• •	• •		• •	• •	1
Office library	• • • •		• •	• •				• •		1
Excavation					• •	• •				2
Treasure Trove			• •	• •		• •			• ,	2
Tours			• •			• •	• •	٠.	• •	2
Tour programm	e for 1916 - 1	7				• •				2
Expenditure on	Conservation	works	• •	• •		• •	• •			2
Conservation	• •	9 4			• •				• •	2
Annual expendi	ture				• •			• •		3
Appendix A.—List	of photo-neg	atives p	repared	during	g 1915-	$\cdot 16$		• •		4
	of new books							• •		9
,, C.—List (of archæologi 16-17.	cal wor	ks proj	posed t	o be u	ndertak	en dur	ing the	year	11
	Statement of									13
,, D (2).—8	Statement of during 1916	expendi 5-16.	ture on	Conse	rvation	works c	arried	out in (Coorg	25
			T.		4					
			Par	r II	2	12.00				
The Origin of the T	ypical Hindu	Templ	e of So	uthern	\mathbf{India}		, ,	• •		28
The Mahendragiri	-						• •	• •		3 5
Conservation Notes	_									39

PART I—ADMINISTRATIVE

അക്കാദമി

ANNUAL PROGRESS REPORT

OF THE

ARCHÆOLOGICAL SURVEY DEPARTMENT SOUTHERN CIRCLE, MADRAS

FOR THE YEAR

1915-1916

Work at Head-quarters

During the month of February, this office was inspected by His Excellency the Governor of Madras and also by Sir John Marshall, c.i.e., the Director-General of Archæology in India.

- 2. In the month of September, at the suggestion of the Director-General of Archæology, I was placed on special duty for a few days to advise His Highness the Nizam's Government with the conservation of the famous Chalukyan temple at Ittagi in the Lingsugar district.
- 3. On the 12th November, I had the honour of conducting their Excellencies Lord and Lady Willingdon and party over the ruined city of Vijayanagar in the Bellary district.
- 4. The plans and section accompanying my article on the Mahendragiri temples Preparation 1 appearing in Part II of this report, and a site plan of the Srisailam temples in the of drawings. Kurnool district, represent the drawings prepared this year. During the rest of his time, the Head Draftsman has been engaged on photographic work which has greatly increased during the last few years.

- 5. During the year, 20 applications for photographs were received from the Photographs public and 479 photo-prints were supplied at a total cost of Rs. 66-2-0 which has since been received and paid into the Bank of Madras to the credit of the Government. Besides these, the usual two sets of photographs accompanying this report, one set for the Director-General of Archæology, one set for the Calcutta Museum and one set for record in this office, amounting to 1,100 prints in all, have been prepared. A descriptive list of these photographs will be found in Appendix A.
- 6. In Part II of this report, I have included illustrated articles on the "Origin of Publications. the Typical Hindu Temple of Southern India," the "Mahendragiri Temples in the Ganjām District" and detailed "Conservation Notes" on repairs carried out during the year under report. The revised "List of Ancient Monuments" has also been completed and is now ready for the Press. The illustrated monograph on "The Ruined City of Vijayanagar" is still under preparation as no extra time for the completion of this additional work was permitted to me during the last hill recess.
- 7. A list of new books and publications acquired during the year is given in Office library. Appendix B.

Excavation.

8. A sum of Rs. 1,000 was allotted in the budget for excavation works but no works of this nature were taken up as the Director-General of Archæology in his letter No. 1370, dated the 19th June 1915, to the Chief Secretary to the Government of Madras proposed that no further excavation works should be undertaken in this Presidency for the present so as to leave more time for the preservation of existing monuments. However, unless this branch of archæology receives attention, there is no hope of recovering and reconstructing the Prehistoric or early history of Southern India and we shall continue to remain as profoundly ignorant of this period as we are at present.

Treasure Trove.

9. The following is a list of treasure-trove cases brought to the notice of this department for an opinion as to whether any portion of the treasure should beacquired on behalf of Government for museum purposes:-

Serial number.	District.	Taluk.	Villøge.	Description of finds.	Whether worth acquiring for Government.
1	South Arcot	Kallakurichi	Viriyur	Stone idols of Venugo- pala, Sattiyabhāmai and Rukmani.	Not worth acquiring.
2	Salem	Atur	Belur	Twelve metal idols and eight metal vessels used for puja pur- poses.	Recommended for acquisition.
3	Tanjore	Tirutturaippūndi.	Jambuvanodai	One copper idol Sivaga- mi Amman.	Do.
4	Rāmnād	Srivilliputtur	Sokkanathanputtur.	One copper image (male and female figure combined).	Do.
5	Tanjore	Kumbakōnam	Mullangudi	Six stone idols Chandra- 86kara, Amman, Sub- ramania, Kalabaira- va, Pakshinamūrti and Chendikesvara.	Do.
6	Salem	Uttangarai	Vellalapatti	Treasure of jewels	Not worth acquiring.
7	Tanjore	Mayavaram	Vellalagaram	23 metal idols	Too decayed to be of any value for the museum.
8	North Arcot	Wandiwash	Kolapallur	Arumugasvan i with pescock, Valliamman, Theivanai Amman, Chandrasekara, Chandikesvara and Paräsakthi Amman.	Not worth acquiring.
9	Vizagapatam	Viravalli	Lopudi	Stone idols	Do.

Tours.

10. As per the orders contained in G.O. No. 1452, Public, dated the 28th November 1912, a monthly statement giving the dates and other particulars of the tours undertaken each month has already been submitted to Government. Altogether 154 days have been spent in camp and the following districts were visited:—Ganjām, Vizagapatam, North Arcot, South Arcot, Bellary, the Nilgiris, Kurnool, Cuddapah, Chittoor, Nellore, Chingleput, Tanjore, Madura, Trichinopoly and Tinnevelly. I also visited Ittagi in the Lingsugar district as mentioned in paragraph 2 above.

Tour

11. A list of the archæological works proposed to be undertaken during 1916-17 programme for 1916-17. is given in Appendix C. I shall endeavour to inspect as many of these works as possible. If time permits, I hope to take up some of the excavation works already sanctioned by Government and mentioned in paragraph 17 of my annual report for 1913-14.

Expenditure on conser-vation works.

12. A statement showing the expenditure on conservation works will be found in Appendix D. The sum of Rs. 35,000 was sanctioned in the budget grant out of which a total sum of Rs. 29,712-15-11 was spent up to the 31st March 1916. sum of Rs. 1,000 allotted for excavation works was surrendered for the reasons cited in paragraph 8 above. The other surrenders were made at the discretion of the Superintending Engineers concerned.

Conservation.

13. Detailed conservation and inspection notes on important repairs proposed during the year have already been submitted to Government and to the Director-General of Archæology in India. A list of the conservation works carried out this year is given in Appendix D. A full report on conservation work will be found in Part II of this report.

14. The expenditure of this department during the year under report has been as follows:—

Annual expenditure.

			RS.	A.	P.
Salary of the Superintendent			7,800	. 0	0
Travelling allowance of the Superintendent			2,994		0
Pay of establishment	• • •		3,734	12	8
Travelling allowance of establishment			. 935	6	9
Contract contingent grant—	* 1				
Supplies and services		•	1,057	5	6
Contingencies					3
Non-contract contingent grant—					
Supplies and services			. 540	4	0
Contingencies			. 1,887	1	1
Personal allowance to establishment in lieu of	compensa	tion for	r 88	5	10
dearness of food.					
	$\mathbf{T}_{\mathbf{C}}$	tal	19,740	11	1

MADRAS, 31st March 1916. A. H. LONGHURST, Superintendent, Archaeological Survey.



APPENDIX A.

LIST OF PHOTO-NEGATIVES PREPARED DURING 1915-16.

CLASS A.

Primitive Stone Monuments and Antiquities.

	Serial Size.			-Subject.	Locality.	District.	
Α.	509	Fall			Two brick and plaster horses with attendants facing the Alagar Nāchi Amman shrine.	Palayajayankonda- sholapuram.	Trichinopoly.
Α.	510	Do.			Large circular barrow	Odugathur	North Arcot.
A.	511	-	• • •	• • • • • • • • • • • • • • • • • • • •	Do	Do	Do.
A.	512	-			Types of pottery vessels found in a tomb.	Do	Do.
Ā.	513	Do.		• • • • • • • • • • • • • • • • • • • •	Do. du.	Do.	Do.
Α.	514	Do.	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	Do. do.	Do	Do.
A.	515	-		••	Do. do.	Do	Do.
A.	516	Do.		••	Corn crushers, palette and pestle found in the tomb.	Do	Do.
A.	517	Do.			Conch ornaments found in the tomb.	$\mathbf{D_0}$	Do.
Ā.	518.	Do.			Conch ornaments and counters	Do	Do.
Ā.	519	-		• • •	Iron implements found in the tomb	Do	Do.
Α.	520	D-			Do. do	Do	Do.

CLASS D.

Hindu Art and Architecture.

	rial nber.		Size.		Subject 46132	Local	ity.		District.
D,	935	Full	••		Copper idol of Vignesvara standing on a bronze pedestal.	Belur			Salem.
D.	936	Do.	••		Copper idol of Vignēsvara standing on a prabāvali.	Do.		••	Do.
D.	937	Do.			Chandikësvara with Amman	Do.		.,	Do.
	938	Do.			Natarājā, Amman and prabāvali	Do.			Do.
	939	Do.	••		Chandrasēkara with Amman in standing posture.	Do.		,.	Do.
D.	940	Do.	••		Umāmahēsvara with Amman and Soma- sundara on a pedestal.	$\mathbf{D_0}$.	••	••	Do.
D.	941	Do.			Idol of Amman	$\mathbf{D_0}$.	• •		Do.
D.	942	Do.			Sri Bāla Nāyaka and Amman on a pedestal.	Do.			$\mathbf{D_0}$.
	943	Do.			Broken bell with stand, receptacle for	Do.			Do.
					burning incense, trident and plate for burning camphor.	•			
D.	944	Do.			Dancing Krishna (front view)	$\mathbf{D_0}$.	٠,		De.
	945	Do.			Dancing Krishna (back view)	Do.	••		Do.
	948	Do.	••	••	Dīpastambha, gendi on a stand and kumbārthi.	Do.	••	••	Do.
D.	947	Do.	••	••	General view of Hazāri Rāma temple, after repair.	Hampi	••	• •	Bellary.
	948	Do.	••	••	Sculpture of a Naga Kanya in Kamalapur bungalow.	Kamalapur	••	••	Do.
D.	949	Do.			Tulasi plant and altar	Triplicane			Madras.
Đ,		Do.		••	General view of the big tower of the Great Temple.	Tanjore	••	• •	Tanjore.
D.		Do.	••	••	East general view of the Mahādēva temple.	Ittagi	• •	• •	Lingsugar. Do.
D.		Do.	••	••	South general view of the tower and porch, Mahādēva temple. Details of the tower from the south,	Do.	••	••	Do.
	953 954	Do.	••	••	Mahādēva temple. Details of south east angle of the Mahā-	Do.	••	••	Do.
D.	955	Do.	• .•	••	deva temple. Do. do.		••	••	Do.
	956	Do.	• •	• •	Do. do.	Do.	••	• •	Do.
		Do.	• •	• •	South view of porch and pillared hall in		• •	• •	Do.
-	957	Do.	••	••	Mahādēva temple.	Do.	••	••	
	958	Do.		• •	Details of pillars in Mahādēva temple	Do.	••		Do.
	959	Do.			Do. do	Do.	• •	• •	Do.
_	960	Do.	• •		Do. do	Do.	• •		Do.
D.		Do.			Do. do	Do.			Do.
D.		Do.	••	• •	Details of doorway, pillared hall in Mahā- dēva temple.	Do.	••	••	Do.
	963	Do.	••	••	Details of porch on north side of the temple.	Do.	••	••	Do.
D.	964	Do.	• •	• •	North general view of Navalinga temple.	Kukkanur	• •	• •	Do.

CLASS D-cent.

Hindu Art and Architecture—cont.

Serial number.		Size.		Subject.	Localit	t y.		District.
D. 965	Full			Details of the shrine doorway, Navalinga	Kukkanur		٠	Lingsugar.
D. 966	Do.	••	,,	temple. Details of pillar in the main shrine,	Do.			Do.
D 967	Do			Navalinga temple. Stone image of an ascetic	Joti			Cuddonoh
D. 967D. 968	Do.	• •	• •	Stone image of an ascetic	Do	• •		Cuddapah.
D. 969 D. 970	Do. Do.	•		Stone image of Sūrya	Do Do		••	Do. Do.
							••	
D. 971D. 972	Do.	• •	• •	General view of old Vishnu temple Details of stambha do.	Sompalli Do.	• • •	• •	Chittoor.
D. 973	Do.	• •	• • •	Mandapa outside the temple	Do.		• •	Do.
D. 974	Do.			Front view of the mandapa inside the	Do.		• •	Do.
D. 975	Do.	• .		Detail of a shrine doorway, old Vishnu	Do.	• •		Do.
D. 976	Do.			temple. Detail of Kalyana mandapa, old Vishnu	Do.	••		Do.
D. 977	Do.			temple. Do. do.	Do.			Do.
D, 978	Po.			East gateway of Pattabirama temple	Hampi			Bellary.
D. 979	Do.	• •	• •	Stone image of Bhīma	Do.	• •	• •	Do.
D. 980	Do.	• •	• •	General view from the south of the temple.	Frisailam	• •	••	Kurnool.
D. 981	Do.	••	••	General view of the outer enclosure wall, from the south-east.	Po.	•	••	Do.
D. 982		• •		South gateway of the temple	Do.	• •	• •	Do.
D. 983	Do.	• •	• •	General view of a group of carved panels on the east face of the outer enclosure	Do.	• •	••	Do.
D. 984	Do.			wall. Details of a niche on the east face of the	Do.			Do.
D. 985	_	• •	••	outer enclosure wall. Sanctum entrance to the old original	Do.		••	Do.
		• •	••	Siva temple.			••	
D. 986	Do.	••	••	Details of sculptured panels from the outer enclosure walls of the Siva temple.	D o.	, ,	••	Do.
D. 987	Do.			Do. do.	$\mathbf{D_0}$.	ļ		Do.
D. 988	Do.	• •	• •	Do. do.	Do.	• •	••	Do.
D. 989 D. 990	Do.	• •	••	Do. do. Do. do.	Do. Do.	• •	• •	Do.
D. 991	Do.	• •	• •	Do. do.	Do.	• •	• •	$\mathbf{D_0}$.
D. 992	Do.			Do. do.	Do.		••	Do.
D. 993	Do.	• •		Do. do.	Do.	• •	• • •	Do.
D. 994	Do.	• •	••	Do. do.	Do. Do.	• •	. ••	υ ₀ .
D. 995 D. 996	Do.	• •	••	Do. do.	${\mathrm{Do.}}^{\mathrm{Do.}}$	• •	• •	Do. Do.
D. 997	Do.	• •	•	Do. do.	Do.	• •	• •	$\mathbf{D_0}$
D. 998	Do.		-,	Do. do.	Po.	••		Do.
D. 999	Do.			Do. do.	Do.	• •	• •	Do.
D. 1000	Do.	• •	••	Do. do.	Do.	• •	Ç 5	\mathbf{p}_{o} .
D. 1001	Do.	• •	•••	De. do. Do. do.	Do.	• •	••	Do.
D. 1002 D. 1003	Do.	••	•••	Do. do.	Do. Do.	••	••	Do. Do.
D. 1004	Do.			Do. do.	Do.	• •	•	Do.
D. 1005	Do.	••		Do. do.	Do.			Do.
D. 1006	Do.	••	••	Do. do.	Do.	• •	• • •	Do.
D. 1007	Do.	• •	• •	Do. do.	Do.	• •	••	Do.
D. 1008 D. 1009	Do.	••	•••	Do. do.	Do. Do.	••	• •	Do. Do.
D. 1009 D. 1010	Do.	• •		Do. do.	D_0 .	• •		Do.
D. 1011	Do.	••		Do. de.	Do.			Do.
D. 1012	Do.	• •		Do. do.	Do.	• •		Do.
D. 1013	Do.	• •	••	Do, do.	Do.	3 •	••	Do.
D. 1014 D. 1015	Do.	• •	••	Do. do.	Do. Do	• •	••	Do. Do.
D. 1015 D. 1016	Do.	••		Stone image of Bringi Maharishi	Do.	• •		Do.
D. 1017	Do.	••		Stone image of female devotee	Do.			Do.
D. 1018	Do.	••		Stone image of Siva and Pārvati seated on a group of five bulls.	Do.	••	••	Do.
D. 1 019	Do.			-Metal images of Siva and Pārvati and Subramanya (Somaskantha).	Do.	••	•••	Do.
D. 1020	Do.	••		Metal image of Siva dancing	Do.	••	••	Do.
D. 1021	Do.		••	Do. do	Do.	••	••	Do.
D. 1022 D. 1023	Do. Do.			Bhima's temple	Mahendragir Do.	i	••	Ganjām. Do.
D. 1025	1							
D. 1024	Do.			ground. South-west general view of Yudhisthira temple.	Do.		, .	Do.

CLASS D-cont.

Hindu Art and Architecture-cont.

	rial nber.		Size.		Subject.	Locality.		District.	
—— D.	1026	Full			Chola inscriptions over the doorway of Yudhisthira temple (duplicate).	Mahendragiri	••	Ganjām.	
D.	1027	Do.			General view of Kunti temple	Do.	••	Do.	
D.	1028	Do.			Details of doorway, Kunti temple	Do.	• •	Do.	
Э.	1029	Do.	• •	• •	Stone chakram found near the Kunti	Do.	• •	Do.	
D.	1030	Do.	••	• 1	temple. General view of Narasimha temple showing Swami and Amman shrines.	Lower Ahobalam	• •,	Kurnool.	
ο.	1031	Do.	`	•,•,	Entrance to unfinished Ranga mandapa in Narasimha temple.	Do.	••	Do.	
υ.	1032	Do.	••	••	Details of pillars in unfinished Ranga mandapa of Narasimha temple.	Do.	••	Do.	
D.	1033	Do.			Do. do.	Do.	• •	Do.	
D.	1034	Do.	• •	••.	Do. do.	Do.	• •	Do. Do.	
Э.	1035	Do.	• •	• •	Lakshmi Narasimha in a pillar of Ranga	Do.	• •	<i>D</i> 0.	
Э.	1036	Do.		••	mandapa, Narasimha temple. Narasimha fighting with Hiranyakasipu in a pillar of Ranga mandapa, Nara-	Do.	•••	Do.	
ο.	1037	Do.			simha temple. Narasimha issuing out of a pillar in	Do.	••	Do.	
D.	1038	Do.			Ranga mandapa, Narasimha temple. East view of first gateway to Narasimha	Do.		Do.	
D .	1039	Do.			temple. West view of first gateway to Narasimha	Do.		Do.	
Ď.	1040	Do.		••	temple. West view of the inner gateway to Nara-	Do.		Do.	
D.	1041	Do.		• •	simha temple. Sculptured figure of Narasimha with two Chenchu women on the inner gateway	Do.		Do.	
D.	1042	Do.			to the Narasimha temple. Details of wooden doors of the inner	Do.	••	Do.	
D.	1043	Do.		••	gateway to the Narasimha temple. Old bazaar in front of Narasimha temple.	Do. Do.		Do. Do.	
D.	1044	Do.	• •	••	Group of mandapas on the east side of the Narasimha temple.	Do.	••	Do.	
).).	1045 1046	Do. Do.	••	••	Do. do. do.	Do.	• •	Do.	
).	1047	Do.	• •	a)	General view of Narasimha temple show- ing the stupi of the temple.	Upper Ahobalam	••	Do,	
ο.	1048	Do.	••	••	General view of Narasimha temple show- ing the river bed on which the temple	Do.	••	Do.	
٥.	1049	Do.			is built. Mandapa facing the main entrance to the	Do.	• •	Do.	
٥.	1050	Do.	••	••	Narasimha temple. Main gateway of the Hindu temple in the fort.	Vellore	• •	North Arcot.	
).	1051	Do.	••	••	Main shrine of the Siva temple in the fort.	Do	••	Do.	
).	1052	Do.	••	••	Main shrine and carved hall of the Siva temple in the fort.	Do	• •	Do.	
D.	1053	Do.		••	Mandapa in the north-west corner of the outer enclosure of the Siva temple in	υο	••	Do.	
D.	1054	Do.	••.	••	the fort. North east portion of the Kalyana mandapa in front of the Siva temple in	Do	••	Do.	
D.	1055	Do.	••	••	the fort. South-west portion of the Kalyana mandapa in front of the Siva temple in	Do	••	Do.	
D.	1 0 5 6	Do.	••	••	the fort. North view of Kalyāna mandapa, in front of the hall of the Siva temple in the	Do	••	Do.	
D.	1057	Do.	••		fort. Details of front pillars in the Kalyana mandapa, in front of the hall, Siva	Do	••	Do	
D	1050	D			temple in the fort.	Do		Do.	
D.	1058 1059	Do.	• •	••	Do. do. Do. do.	Do	• •	Do.	
).	1060	110.	• •	••	Group of warriors on the pillars of the	Do		Do.	
					Kalyana mandapa in front of the hall,				
`	1021	Da			Siva temple in the fort. Do. do.	Do		Do.	
),),	1061 1062	Do. Do.	••	••	Sita on the base of a pillar of Kalyana mantapa fn front of the hall, Siva	Do	••	Do.	
		} •			temple in the fort.	_			
D.	1063	Do.	••	••	Female figure and Rishis on the base of a pillar of the Kalyana mandapa in front of the Hall in the Siva temple in the	Do	••	Do.	
D.	1064	Do.		••	Fort. Rāmā on the base of a pillar of the Kal- yāna mandapa in front of the Ha!! in	Do	••	Do.	

CLASS D-cont.

Hindu Art and Architecture—cont.

Serial number.	Size.			Subject.	Localid	Localit y .		
D. 1065	Full		•••	Ganesa on the base of a pillar of the Kalyana mandapa in front of the Hall	Vellore		*	North Arcot.
D. 1036	Do.	€0	••	in the Siva temple in the Fort. Interior view of the Kalyana mandapa in front of the Hall in the Siva temple in the Fort.	Do.	••	••	Do.
D. 1067	Do.	••	••	Details of ceiling over the Kalyana mandapa in front of the Hall in the Siva temple in the Fort.	Do.	••	••	Do.
D. 1068	Do.	••	••	Details of panels carved on the first plat- form in Kalyana mandapa in front of the Hall in the Siva temple in the Fort	Do.	••	••	Do.
D. 1069	Do.			Do. do.	Do.			$\mathbf{D_0}$.
D. 1070	Do.	••		Do. do.	Do.			\mathbf{D}_{0} .
D. 1071	Do.		•.	General view of the upper platform in Kalyana mandapa in front of the Hall in the Siva temple in the Fort.	Do.	••	••	Do.
D. 1072	Do.	••	••	Details of pedestal on upper platform in Kalyāna mandapa in front of the Hall in the Siva temple in the Fort.	Do.	• •	, ,	Do.
D. 1073	Do.	••		Details of sculptures in the North wall of the Kalyana mandapa in front of the Hall in the Siva temple in the Fort.	Do.	••	••	Do.
D. 1074	Do.	••	••	Details of moulding and panels in the Kalyana mandapa in front of the Hall in the Siya temple in the Fort.	Do.	••	••	Do.
D. 1075	Do.	••	••	Details of sculptures in the South west wall of Kalyana mandapa in front of the Hall in the Siva temple in the Fort.	Do.	••	••	Do.
D. 107 6	Do.	••	••	Details of inner side of the carved eaves in Kalyāna mandapa in front of the Hall in the Siva temple in the Fort.	. Do.	••	••	Do.
D. 1077	Do.		••	Front view of Arumugasvami on a peacock found in a treasure trove.	Kolappallur	٠٠	••	Do.
D. 1078	Do.	• •	••	Back view of Ārumugasvami on a peacock found in a treasure trove.	Do.	••	••	Do.
D. 1079	Do.	••	••	Group of six images in a treasure trove viz. Arumugasvami on a peacock, Valliamman, Theivanai Amman, Chandrasēkara, Chandikēsvara, and Parāsakthi Amman.	Do.	••	••	Do.

CLASS E.

Muhammadan Art and Architecture.

	Serial Size.			Subject.	Locality.	Dist ict.		
E. E. E.	47 48 49 50 51	Full Do. Do. Do. Do.	••	•	Front view of Purkota Masjid Tomb of Bismilla Shāvali Inscriptions over the doorway of the Tomb of Bismilla Shāvali General view of mosque in the citadel General view of ornamental tank in the		••	Cuddapah. Do. Do. North Arcot. Do.
E.	52	Do.	••	••	citadel. General view showing view of old cannon.	Do	••	Do.

CLASS F.

Indo-Saracenic Art and Architecture.

	erial mber. Size.			dubject.	Loc	alit y .	District.		
F.	46	Full		• •	East view of Nayak's Darbar Hall in the Palace after repairs.	Tanjore	••	••	Tanjore.
F.	47	Do.	••	••	Gopala Raja's Palace, showing outer facade from the road.	Kurnool	• •	••	Kurnool.
F.	48	Do.	• •		Remains of Gopala Raja's Palace	Do.	• •		Do.
F.	49	Do.			Gopāla Rāja's gateway	Do.			Do.
F.	50	Do.			Didde Darwaza	Do.		• •	Do.
F.	51	-	• •		Darbar Hall in the old Nawab's Palace	Do.			Do.
F. F. F. F.	52	1 5	••	••	The Asari Sheriff's building in the enclosure of the old Nawab's Palace.	Do.	••	••	Do.

CLASS G.

Historical Forts and European Monuments.

	rial b er.		Size.		Subject.	Localit	y.		District.
<u> </u>	124	Full			General view of Rājagiri Hill with	Gingee			South Arcot.
•		Lun	••	••	Venkataramana temple in the fore-	Gingee	••	••	South Alcoh.
G.	125	Do.			General view of Krishnagiri Hill	Do.			Do.
G.	126	Do.	••	••	General view of Chandrayan Drug from Krishnagiri Hill.	Do.	••	••	Do.
G.	127	Do.			Pondicherry Gate and Royal Battery	Do.			Do.
G.	128	Dø.		• •	Pondicherry Gate and Inner Gateway	Do.			Do.
G.	129	Do.		• •	Arcot (or Vellore) Gate	Do.			Do.
G.	130	Do.			Ruined Fortifications on Krishnagiri Hill.	Do.		••	Do.
G.	131	Do.			Do. do.	Do.			Do.
G.	132	Do.			Granary on the Krishnagiri Hill	Do.			Do.
G.	133	Do.	••	••	West view of the Audience Chamber on the Krishnagiri Hill.	Do.	• •	••	Do.
G.	134	Do.			East view of the Audience Chamber on	Do			Do.
					the Krishnagiri Hill showing Ranga nadha temple.		••	••	Do.
G.	135	Do.			Ruined mandapa on the Krishnagiri Hill.	Do.			Do.
G.	136	Do:	• •	• •	General view of Kalyana Mahal	Do.			Do.
G.	137	Do.	••	••	General view of Sadat Ulla Khan's Mosque.	Do.	••	••	Do.
G.	138	Do.	• •	• •	Gymnasium Hall	Do			Do.
G.	1 39	Do.	• •	• •	Ruined temples in the inner Fort	Do.			Do.
G.	140	Do.		••	Prisoner's Well	Do.			1)0.
G.	141	Do.			Chakkaraikulam (Tank)	1,0.			Do.
G.	142	Do.		• •	Chettikulam (Tank)	Do.	• •		Do.
G.	143	Do.		••	Fortifications on the west side of the Fort.	Do.	••	••	Do.
G.	144	Do.	••	••	Main entrance to the West Gateway of the Fort.	Siddhavatta	ım	••	Cuddapah.
G.	145	Do.		• •	West Gateway of the Fort from east	Do.		• •	Do.
Ġ.	146	Do.			East Gateway of the Fort from east	Do.			Do.
G.	147	Do.	• •		General view of the Fort from east	Do.			Do.
G.	148	Do.			Bastion of the Fort from the east	Do.			Do.
G.	149	Do.		••	General view of the Fort showing the meat from the east.	Do.		••	Do.
G.	150	Do.	••	••	Group of stone cannon balls inside the Fort.	Do.		••	Do.
G.	151	Do.			Delhi Gate from the south	Arcot			North Arcot.
G.	152	Do.		• •	Delhi Gate from the north	Do			Do.
G.	153	Do.		.,	North-eastern portion of the Shaharpana.	Do		• •	Do.
G.	154	Do.		• •	Domed gateway on the east side of the citadel.	Hampi	• • -	••	Bellary.
G.	155	Do.	• •	••	Ruined Gateway on east side of the citadel.	Do.	••	••	Do.
G.	156	Do.	••	••	North-east corner of the moat, Vellore Fort.	Vellore	••	••	North Arcot.
G.	157	Do.			North-east bastion, Vellore Fort	Do.			Do.
Ğ.	158	Do.			East view of the bastion, Vellore Fort	Do.			Do.
Ğ.	159	Do.		••	East view showing the moat, Vellore Fort.	Do.			Do.
Ğ.	160	Do.			East view of the Vellore Fort	Do.			Do .
G.	161	Do.			South-east end of the moat, Vellore Fort.	Do.			Do

CLASS I.

Miscellaneous

Serial umber	5126.			Subject.	Locality.	District.		
I. 3	0 1	Full			Foundation Stone	Hulibidu ,.	.,	Bellary.
I. 3	1	Do.	••	•	General view of the elephant and horse in Avyanar temple.	Areot	• •	North Arcot
I. 3	2	Do.	••	••	General view of a hut of Yerukala encampment.	Repur	••	Nellor
I. 3	3	Do.	••	••	Detail of a hut of Yerukala encamp- ment.	Do	••	Do.
1. 3	4	Do.	••	••	General view of the causeway to the Kistna river.	Srisailam	••	Kurnoel.
I. 3	5	Do.			View of the Kistna river	Do		Do.
I. 3	6	Do.			Do	Do		Do.
Ī. 3		Do.		••	View from the Mahendragiri Hill looking north.	Mabendragiri	••	Ganjām.
` I. 3	8	Do.	••	••	View from the Mahendragiri Hill looking south.	Do.	••	Do.
1. 3	9	Do.	••	٠,	View from the Mahendragiri Hill looking north-east.	Do.	••	Do.
T. 4	0	Do.	••	• -	View from the Mahendragiri Hill looking north-east.	Do.	••	Do.
I. 4	1	Do.	••	••	View of a stream near the Narasimha temple.	Upper Ahobalam	••	Kurnool.

APPENDIX B.

The following is a list of books added to this office library during the year 1915-16.

1. Indian Antiquary (Current numbers).

2. Epigraphia Indica (

3. The Journal of the Royal Asiatic Society (Quarterly).

4. The Journal of Indian Art and Industry.

The Journal of the Royal Anthropological Institute, Volume XLV.

6. The Journal of the Mythic Society (Quarterly), Volumes I to V and Volume VI, Parts 1 and 2.

7. The Quarterly Civil List of officers for Madras Presidency.

8. The Quarterly Civil List of Archæological Survey Department.
9. Elements of Hindu Iconography by T. A. Gopinatha Rao, M.A., Volume I, Parts 1

10. South Indian Bronzes by O. C. Gangoly.

11. Ancient and Medieval Architecture of India by E. B. Havell.

12. The Eastern Libyans by Oric Bates.

- 13. Notes on the Ancient Geography of Gandhara by A. Foucher.
- 14. The Rebel Commandant Yusuf Khan by S. C. Hill.

15. Civil Service Regulations (Reprint), fifth edition.

16. Appendices to the Civil Service Regulations, fifth edition.

17. Civil Budget Estimate (1915-16).

18. The Madras Code, Volume I.

19. Indian Education in 1913-14, Government of India Publication.

20. History of Vijayanagar by Suryanarayan Rao.

- 21. List of Photo Negatives in the office of the Superintendent, Hindu and Buddhist Monuments, Northern Circle.
- 22. List of Drawings of Archæological buildings in the Office of the Superintendent, Muhammadan and British Monuments, Northern Circle, United Provinces.

23. A descriptive catalogue of the Sanskrit Manuscripts.

24. Catalogue of Prehistoric antiquities by A. Rea.

25. Catalogue of Indian Prehistoric and Protohistoric antiquities by Bruce Foote.

26. Catalogue of the Connemara Public Library.

27. Classified catalogue of the Library of the Archæological Department, Frontier circle.

28. Monograph on Lean Exhibition Coronation Durbar, 1911.29. The Lawrence Asylum Almanac for 1916.

30. The Madras Medical Registration Act, 19!5, with list of registered medical practitioners in the Madras Presidency.

31. Night Photography by R. Dykes. 32. Report of the Maha Bodhi Society.

33. Classified catalogue of the Library of the Peshawar Museum.

34. Postal Guide for 1915.

35. Report of the Chief Inspector of Mines in India for 1914. 36. Pallava inscriptions at Panamalai by G. Jouvean-Dubreuil.

- 37. Indian Chronology B.C. 1—A.D. 2000, by L. D. Swamikannu Pillai.
 38. Abstract of the rules relating to Public Service Examinations in the Madras Presidency.
- 39. List of Sanskrit, Jain and Hindu Manuscripts purchased by Government of Allahabad and deposited in Sanskrit College, Benares.

40. Publications of the Department of Education, January 1911 to August 1914.

41. Ceylon Administration Report, 1914.

42. Administration Report, Madras Presidency, for the year 1914-15.

- 43. Annual Report of Archæology by the Director-General of Archæology for the year 1911-12.
- 44. Annual Report of the Archæological Survey Department, Southern Circle, for 1914-15.
- 45. Annual Report of the Assistant Archæological Superintendent for Epigraphy, Southern Circle, for 1914-15
- 46. Annual Progress Report of the Archæological Survey Department, Northern Circle, for the year ending 31st March 1914 (Hindu and Buddhist Monuments).
- 47. Annual Progress Report of the Superintendent, Muhammadan and British Monuments, Northern Circle, for the year ending 31st March 1914.
- 48. Annual Report of Archæology by the Director-General of Archæology in India for 1912-13, Part I.

49. Annual Report of Archæological Survey, Burma Circle, for the year ending 31st March 1915.

50. Annual Report of Archæological Survey, Frontier Circle, for the year 1914-15.

51. Annual Report of Archæological Survey, Eastern Circle, for the year 1914-15. 52. Annual Report of Archæological Survey, Western Circle, for the year ending 31st March 1915.

53. Annual Progress Report of the Saperintendent, Muhammadan and British Monuments, Northern Circle, for the year ending 31st March 1915.

54. The following District Gazetteers, Part II:-

North Arcot, South Arcot, Anantapur, Anjengo, Bellary, South Canara, Chingleput, Chittoor, Coimbatore, Cuddapah, Gōdāvari, Guntūr, Kistna, Kurnool, Madura, Malabar, Nellore, The Nilgiris, Rāmnād, Salem, Tanjore, Tinnevelly, Trichinopoly and Vizagapatam.

55. The following taluk maps of the districts-

Anantapur district	••	Madakasira.	Tanjore district	<	Tanjore. Tirutturaippūndi.
North Arcot district	• •	Tiruvannāmalai.	a anjoro district		Pattukkõttai. Kõvilpatti.
Ganjām district	••	Tekkali zamindari.	Tinnevelly district	<	Srīvaikuntam. Tinnevelly.
Gōdāvari district	••	Rajahmundry.			Tiruchendūr.



APPENDIX C.

List of archwological works proposed to be undertaken during the year 1916-17.

No.	ul Distri	ict.		Name of monument and nature of work.		Grant for 1916-17
				I Circle.		RS.
						7.00
1.	Vizagapa	am	• • •	Annual repairs to Buddhist monastery, Sankaram	3.4.4	100
2.	Do.			Pay of watchman for Buddhist monastery, Sankaram	•••	72
3.	Do.			Annual repairs to Buddhist monastery, Ramatirtham	•••	100
4.	Do.			Pay of watchman for Buddhist monastery, Ramatirtham	•••	72
				II Circle.		
5.	Kistna	a • =	•••	Repairs to Akkanna Madanna caves, Bezwada	•••	1
				Repairs to Twin caves, Bezwada		٤
				Repairs to Caves on the west of Bezwada hill, Bezwada	• • •	1
				Repairs to Govinda cave, Bezwada		1
6.	Do.	• • •	• • •	Repairs to caves on the hill, Mogalrajapuram	~ *	′ 4
7.	Do.	•••		Repairs to Jalakesvara and Visveswara temples, Ghantasala	• • •	20
8.	Do.			Repairs to Buddhist stupa in the mound, Ghantasala	•••	10
9.	Do.			Repairs to Dutch cemetery, Bandar		18
10.	Do.			Repairs to Lanja dibba with remains of Buddhist stupa a	\mathbf{and}	
				ancient village site, Gudivada	•••	1
11.	Do.		•••	Repairs to Buddhist stupa, Jaggayyapeta		20
12.	D_0 .	•••	•••	Repairs to Buddhist caves, Guntapalle		250
	Guntūr	•••	•••	Pay of watchman for Buddhist stupa, Amaravati		66
. • •	G 444444	•••	•••	ALCOHOL MALANA SECTION		
				III Circle.		
14.	Anantapı	ır	***	Repairs to bastions and gateway, Madakasira	• • •	15
5.	Do.			Repairs to large well, Ratnagiri	•••	20
l 6.	Do.			Repairs to Sethuthirtham well, Penukonda	• • •	ő
17.	Do.			Repairs to fort, Penukonda		10
18.	Do.		•••	Repairs to Gagan Mahal. Penukonda	•••	5
9.	$\mathbf{p}_{\mathbf{o}}$.		* 4 2	Repairs to Iswara temple, Penukonda	•••	20
20.	$\mathbf{D_0}$.				elđ,	
				renukonda		50
21.	Do.			Repairs to Rama temple, Penukonda	•••	100
22.	Do.			Repairs to Rama's bastion, Penukonda		5
23.	Do.		•••	Repairs to a stambha in the compound of Sub-Collector's off	ice,	18
24.	Do.			Pay of two watchmen for ancient monuments at Penukonda	•••	178
	-		• • •	Annual repairs to Sir Thomas Munro's house, Anantapur		
25.	Do.		•••		•••	250
26.	Do.		•••	Maintenance and repairs to the Rock Fort, Gooty	•••	200
27.	Do.			Repairs to Rama temple, Tadpatri	•••	10
	Bellary	•••	•••	Repairs to Vittala temple, Hampi	• • -	800
29.	\mathbf{p}_{0} .	• • •	• • •	Repairs to Pattabirama temple, Hampi	• •	500
30.	$\mathbf{p}_{\mathbf{o}}$.	•••		Repairs to Achyutaraya temple, Hampi	• • •	1,000
31.	$\mathbf{p}_{\mathbf{o}}$.	•••	•••	Repairs to Krishna temple, Hampi	•••	200
32.	Do.	•••	•••	Repairs to Anantasayana temple, Hampi	• • •	200
33.	$\mathbf{p}_{\mathbf{o}}$.	•••	• • •	Repairs to Sasivikal Ganesa temple, Hampi	•••	5
34.	Do.	•••	•••	Repairs to large public bath or tank, Hampi	• • •	100
35.	Do.		• • •	Repairs to elephant stables, Hampi	•••	230
36.	Do.	•••		Repairs to Hazara Ramachandra temple, Hampi		350
37.	Do.			Repairs to Jain temple, Hampi	• • •	100
88.	\mathcal{D}_0 .	• • •		Repairs to roads in Hampi ruius, Hampi		333
39.	Do.	• • •	•••	Maintenance of watchmen, Hampi		650
10.	Do.		•••	Repairs to Malyavanta Ragunatha temple, Hampi		300
11.	Do.	•••	•••	Repairs to Muhammadan Durga at Kaderampur, Hampi		100
12.	Do.		•••	Repairs to Audience Hall, Hampi	• • • •	70
13.	Do.		•••	Repairs to group of buildings in the Muhammadan enclosur	re,	. (
				Hampi	•••	28
44 .	Cuddapah	ı		Repairs to temples on the Pushpagiri hills, Pushpagiri	• • •	500
45.	Do.		• • •	Repairs to ancient well "Bogandani bavi," Rajampet		100
			• • •	Repairs to Nawab's Towers, Cuddapah		5(
16.	Do.			Liopails to Fallabs Loucis, Cadaapal		
	Do.			Repairs to Syed Ahmad Sahib's Masjid, Cuddapah		50

List of archæological works proposed to be undertaken during the year 1916-17-cont.

	. Distric	t.		Name of monument and nature of work,			Gran for 1 916 –
				IV Circle.			R
	35 1 1						
	Malabar	•••	• • •	Annual repairs to the Fort, Tellicherry		• • •	1
0.	Do.	•••	•••	Do. do. Palghat	•••	• • •	ã,
1.	Do.	***	•••	Repairs to Jain temple, Wynaad	•••	• • •	1 0
	South Ca	nara	•••	Repairs to fort, Bekal	•••	• • •	1,0
3.	Do.		•••	Repairs to the Great Chandranath temple, Mudabi	d r 1	•••	3
4.	Do.		•••	Repairs to the hill fort at Jamalabad, Nada	•••	• • •	7
	Nilgiri	•••	•••	Repairs to ruined fort at Hulikaldrug, Coonoor		• • •	
6.	Do.	•••	•••	Repairs to Group of sculptured dolmens at Batlad	a Act	ieni,	,
7.	\mathbf{D}_{0}		•••	Repairs to sculptured dolmens at Melkunda, Coono	or	• • • •	
3.	Do.		•••	Repairs to large dolmens at Banagudi shola of		nerri	
•		•••	•••	Coonoor		•	
9.	Trichino	olv	•••	Repairs to hill fort, Namakkal	•••	•••	1
0.	Do.	3019	•••	Danaina da Manasinala kannala Manasalasi		•••	2
Ĺ.	Do.		••	Repairs to Ranganatha temple, Namakkal	• • •	• • •	2
	Salem			Donoine to the fact San basidance	•••	•••	ź
3. 3.	\mathbf{D}_0 .	•••	•••	Do de harm	•••	•••	<u>ا</u> د
•	٠٠٠٠	•••	•••		•••	•••	^
	36 .			V Girole.			
	Madras	• • •	•••	Repairs to the old Madras Town wall, Madras		• • •	1
Ó.	Do.	•••	• • •	Repairs to Obelisk standing to the north of	the we	estern	ı
				extremity of the old Madras Town wall, Madras	•••		
3.	Do.	•••	• • •	Repairs to slab in R.S. No. 1764, Madras	•••	• • •	
٠.	\mathbf{Do} .	•••	•••	Repairs to pillar R.S. No. 1793, Madras		• • •	
	Do.		•••	Do. do. No. 1816, Madras	•••	• • •	
١.	Do.		•••	Repairs to Cornwallis Memorial, Madras			
	Chinglep	a t	2	Repairs and conservation of ancient monuments	. Mah	ab a li-	
Ť	0 1			puram			5
	Do.			General repairs to the archæological works, Mahak	alinur	am.	1,0
)	\mathbf{Do} .		•••	Improvements to the five Raths, Mahabalipuram			
3.	Do.		•••	Annual repairs to Ther Mahal, Chingleput	•••		2
Į.	Do.		•••	Repairs to Munkudumisvara temple, Kalattur	•••		ĵ
	Nellore			Lump sum provision for archeological works		llovo	_
•				division, Nellore			
				VI Circle.	•••	•••	
	3.5 3						
	Madura	•••	•••	Repairs to Koilpatti temple, Koilpatti	***	•••	
•	D_0 .	•••	•••	Pay of watchman for rock Fort, Dindigul	•••	• • •	
	Trichinop	oly	•••	Repairs to fort gateway and Prestons Battery, Tric	${f hin}_0{f p}_0$	ly.	1,1
	\mathbf{D}_{0} .		• • •	Repairs to Valisvara temple, Valikondapuram	• • •		1
).	Tinnevell	У	•••	Collecting and stacking the inscribed stones of	the \mathbf{r} u	$_{ m ined}$	
				Vishnu temple, Agaram		- • •]
	Do.		•••	Pay of watchman for prehistoric remains, Adichan	allur	• • •	
,	Do.		94-	Repairs to Kanakasabhai temple, Karisuladamanga	$_{ m lam}$	•••	2
				VII Circle.			
,	Chittan						
	Chittoor	oot	•••	Annual repairs to Chendragiri Mahal, Chendragiri		•••	è
	North A	CO V	•••	Pay of watchman for the Delhi gate, Arcot	•••	•••	
	Do.		•••	Repairs to the fort, Vellore	•••	•••	4
	Do.		• • •	Repairs to the Hindu temple in the fort, Vellore	• • •	• • •	Č
٠.	Do.		•••	Repairs to Vishnu temple, Ukkal	- •		1
3.	Do.		•••	Repairs to Baradwajesvara temple, Pudupadi	•••	•••	
) .	D_0 .	,	•••	Repairs to the fort, Wandiwash		•••	2
).	Do.	1	• • •	Repairs to relies in the old fort, Arcot		4	1,0
•		cot	•••	Repairs to Gingee fort, Gingee	•••	• • •	2,0
	Do.		•••	Pay of two watchmen for Gingee fort, Gingee	•••	• • •	1
	Tanjore	•••	•••	Repairs to Krishna Vilas tank, in the Palace, Tanj	ore		2
ŀ.		•••	•••	Repairs to the front tower of the great temple	e, Tan	ijore	ž,
j.	Do.	•••	• • •	Maintenance of the Sivaganga little fort, Tanjore	• • •	• • • •	1
j.	Do.	• • >		Repairs to the Schwartz church, Tanjore	• • •	•••	1
7.	$\mathbf{D}_{0}.$	•••	•••	Repairs to the subterranean passage, Nidamangala	m	• • •	
)	Do.	•••	•••	Repairs to Dutch cemetery, Negapatam	• • •	•••	1
3.	T	•••	•••	Contingency for urgent archæological repairs	•••	• • •	3,8
). }.	Do.	•••	•••	C 0 7 - 1		• • •	
	Do.	•••	•••	, , , , , , , , , , , , , , , , , , ,	Total	•••	

APPENDIX D (1). Statement of expenditure on Conservation work carried out during the year 1915-16.

Number.	District.	Taluk.	.•	Place.	Name of	of monument.	Description of repairs done during 1915-16.	pairs don e d	uring 1915-16.	Amount sanotioned.	Actual expenditure.	.e. Remarks.
							First Circle.					
	Vizagapatam	Anakapalle	:	Sankaram	Buddhist remains	remains	Annual repairs.—Repairs		to Buddhist	E 100	RS. A.	P. 0
01 80	Do. Do.	Do. Bamatirtham	::	Do. Ramatirtham	.:	Do	monastery. Pay of watchman Annual repairs.	-Repairs	to Buddhist	t 72	64 0 73 0	0 0
410	Do. Gōdāvari	Bajshmundry	::	Do. Rajahmundry	Boyal M.	Do Mosque	monastery. Pay of watchman Repairing compound wall and collection of materials for reconstruction of terrace roofing. The expenditure during the year is in adjustment of liabilities for work done during the previous year.	nund wall an reconstruct expenditure ent of liable previous y	ad collection of ion of terrace during the year	1,72 r r K	72 0 112 6	The work is stopped and the monument is deleted from the List of Ancient Monuments—vide G.O. No. 1802, dated 13th December 1915.
						/68	Second Circle.	M				
9	Guntur	Sattenapalli	:	Amaravati	Mound of Buddhi other r	ound containing a Buddhist stupa and other remains	Maintaining a watcher,	atcher,	:		0 09	0 A
I ~	Kistna	Bezwada.,	•	Bezwada ,	Cave we wada	west of Bez-	Craoks grouted with cement and concrete soft broken stone in surk mortar laid on	with cemen ne in surki	cement and concrete surki mortar laid on	9	10 0	ourng the whole year. The repairs do e are of the nature of ordinary repairs.
∞	Do:	Do	:	Mogalrajapuram		nujabilam cave). tves on the hill	the top of the caye.	cave.			•	It is reported that no repairs were necessary for the caves on the Mogalrajapuram hill and that the whole grant was spent on the cave west of Beawada hill to avoid lapse of grant.
	•						Third Oircle.			,	;	•
o s .	Anantapur	Hindupur	•	Gorantla	Vishnu temple	temple	88	ation, filling sering top of steps of semoving a sent and a	moving vegetation, filling in cavities with concrete, plastering top of roofing. Providing raised steps of stones to the 3 entrances. Removing and repacking fallen revetment and all other petty	300 3 3 1 1 2 3 3 0 0	300	θ ',
4	Do.	Madakasira	*	Madakasira	Gateway bastion fort.	Gateway and 2 large bastions of the hill fort.		provision in ried out dur ken tops of tar. Clearii tions. Poin grouting ai ws and all ctl	repairs as per provision made in the surmate were carried out during the year. Douisding broken tops of parapet with brick in mortar. Clearing debris from top of all bastions. Pointing with surki mortar after grouting and filling with chips all hollows and all other items of the estimate except flight of steps were done in the year.	- 05 05 06	0 96	0

Statement of expenditure on Conservation work carried out during the year 1915-16-cont.

Remarks.					The expenditure on this work which was originally sanotioned under Provincial Givil Budget Arohæological Repairs—is now written back to Provincial Givil Budget Repairs, as the estimate has been—since sanctioned under this had					
Actual expenditure.		BS. A. P.	107 0 0	11 0 0	— 14 5 0 0	0 0 29	168 0 0	5 0 0 46 0 0	0 0 26	594 0 0
Amount sanctioned.	,	RS.	08	10	- 146	39	168	75	120	263
Description of repairs done during 1915–16.	□ Third Circle—cont.		Employment of watchers to clear vegetation on archæological works.	Repairs to Gagan Mahal. Estimate Rs. 135 C. R. No. 170 of 1919 1919	Roofing with full and half pot tiles and painting.	Annual Repairs.—Whitewashing and colour washing two coats, sundry plastering and cleaning doors and windows with wood oiling.	(1) Annual Repairs.—Removing vegetation repairs to gates Nos. 5 and 6 such as reconstructing fallen portions, grouting the joints and plastering and repairing the front gate between pillars and Fort.	(2) Providing a ladder to watchers (3) Maintaining two watchmon to look after the Fort.	Repairs.—Kemoving the existing dilapidated semi-circular coping 3' dr. of stone in mud and rebuilding with stone in rad plastered over 2" thick pointing with churam, removing vegetation, plastering here and there and clearing rubbish.	Bive watchmen were employed to look after all the ancient monuments in Hampi ruins and one watchman for Vittala temple. The work of the watchman was supervised by a headwatcher. Vegetation was removed periolically from all the monuments, and pathways obsered.
Name of monument.	2		Watchers to look after all archæological works at Penu-konda.	Gagan Mahal	Do.	Sir Thomas Munro's House.	Fort and its buildings including also the fortifications at the foot of the [1i]].		Siva temple	Euployment of watch- men to look after Hampi ruins, Estimate Rs. 620.
Place.			Penukonda	Do	Do. :	Anantapur	Gooty		Kambaduru	Hampi
Taluk.			Penukonda	Do	 	Anantapur	Gooty		Kalyandrug	Hospet
Distriot.			Anantapur	Do.	Do. :	Do	Do		Do:	Bellary
Number.			Ħ	12	. 13	14	16		16	17

Remarks. 349 0 0 | Work completed. P. Work completed. Do. Do. 0 0 0 expenditure. 392 O 0 0 0 Actual 653 300 771 Statement of expenditure on Conservation work carried out during the year 1915-16—conf. Amount sanctioned. RS. 380 298 692 653 350 The fallen compound wall of cut stone was set right. The weathered portions on top of gopuram at south and over the temple of goldess were underpinned with briok in mortar and plastered with lime mortar. The floor of front mandapa was plastered with cement, as also the walls all round the gopuran was plastered with lime mortar; the holes and weatleard portions having been made up with brick in mortar. All open fefits have been grouted and pointed with cement. Whitewash on the pillars at front mandapa was removed. Ground all round in temple was sloped for drainage of rain water. Vegetation from the top of wall all round was removed.

The gopuram on the eastern side was thoroughly repaired, The overhanging thoroughly repaired. The overhanging masonry was supported on the inside by the insertion of lintel stones and by masonry pillars constructed over two cut The branch and so walls in front and all round at top were patched up and plastered. Walls all round were pointed with lime mortar. Vegetation from the top far away and stacked.

The top of walls was made watertight by laying concrete plaster over. Vegetation from walls all round Durgah and tomb stone platforms resting on rolled steel girders. The interior was plastered with was rooted out. Ground all round was sloped for drainage and gravelled over. I he interior of mosque was cleaned. The loose stones lying all round were removed was rooted out. The joints pointed with lime mortar. Ground all round Durgah gravelled over. A pathway was opened from the road to both the structures and and tomb was sloped for drainage and Description of repairs done during 1915-16. Third Oirole-cont. gravelled over. ime mortar. main temple. Large ruined temple at Ananthasayana Gudi. Malyavanta Raghu-Mosque in Dannaick's Muhammadan tombs Name of monument. Pattabhirama temple. at Kadiram river. natha temple. enclosure. : : : : : : : : : Place. Hampi Do. Do, ů. ů, : : : : . : Taluk. : : : : Hospet Do. Do. Do. ņ. : : : . Bellary ... District. : : : Do. ů. Do. ë. Number. 18 19 20 21 22

Statement of expenditure on Conservation work carried out during the year 1915-16-cont.

Disting			Taluk.		<u>Б</u>	Place.		Name of monument.	Description of repairs done during 1915-16.	Amount sanctioned.	Actual expenditure.	Remarks.
								иZ	Third Girels—cont.			
:	•		Hospei	:	Hampi	:	:	Vittala temple	The weathered pillars in front of main temple were supported by the construction of two out stone pillars. The floor of front mandapa and south mandapa was pointed with cement. A pathway was opened from the northern entrance to Vishnu temple at north-west. Vegetation was rooted out in front and ground sloped for drainage and gravelled over. The arched openings at top on the couth and eastern gopurans were removed by the insertion of stone lintels.	436 436	BS. A. P. 414 0 0	
:			Q	:	Do.	:	:	Group of buildings in Zanana enclosure.	Ē	302	302 0 0	Work completed.
		:	Do.		Ď.	:	:	Chandrasēkara temple, ```	All open joints around temple were grouted and pointed with coment. The arched openings over the eastern gopuram were supported with stone lintels. A pathway was opened from the tomple to meet the way to cotagonal bath and gravelled	165	166 0 0	Do.
•		:	Do	:	Do.	:	:	Providing name boards to anoient monuments.	over. Towns and the old name boards were repaired and repaired wherever necessary.	02	71 0 0	Do.
:	-	:	. Do.	•	Do.	:	:	Audience Hall, Hampi Ruins.	The steps on the northern side were set right and joints grouted and pointed with lime mortar. Joints on the northern and eastern sides were pointed with lime mortar. The undermined portion on the southern side was filled up with earth.	99	64 0 0	Do.
•		:	Do	:	. Do.	:	:	Repairs to roads in Hampi Ruins.	I Loose stones were stacked aloof. Excavation of side channel and gravel collection were almost completed. Clearing of prickly pear by road side was progressing.	200	180 0 0	In progress.

Statement of expenditure on Conservation work carried out during the year 1915-16-cont.

	Distri ot.		Taluk.		Pla06.		Name of monumont.	Description of repairs done during 1915-16.	Amount sanctioned.	Actual expenditure.	Romarks.
İ							Th	Third Girele—cont.			
		_							. B.8.	R8. A. P.	
elle	Bellary	:	Hospet	Hampi	idi	:	Laying cut a pathway in Muhammadan enclosure.	A new pathway is being opened from the Muhammadan watch tower to Muhammadan mosque in Dannaick's enclosure. Earthwork and construction of rough stone wall were almost completed. Vegelation along the pathway was removed.	100	72 0 0	Works completed.
ш	Do	:	Do	Do.	·	:	Repairs to road leading to Vittala	Formation of road to the temple during His Excellency's visit to Humpi Ruins.	122	122 0 (0 Do.
Н	Do	:	Do	. Do.	:	:	Pattabhirama temple	Ξ	- 122	- 122 0	0 Do.
Η	Do	-:	ъ	Adoni	i	:	Government ancient	ہم	90	0 69	0 Do.
-		:	Harpanahalli	Bagali	"Ii	:_	monument. Kallesvara temple	monuments. The dilapidated compound wall was rebuilt. The revetment on the tank side was	1,170	1,174 0	0
	D.	:	Hadagalli	Tem	Ts m brahalli	:	Ancient well	with cement. Jeaky portions on the top of front mandapa of main temple were patched up. The southern wall of the main temple which had gone out of plumb was supported with a masonry buttrees. The compound around the temple was cleared of earth and debris and gravel was spread all round the main temple and front mandapa and over the revetment on the tank side. All the sub-shrines were cleaned and the walls were repached. Except a door for the gateway all the other works were completed. All the joints of steining all round were grouted and pointed. New out stone steps were constructed at the edge of water. The broken beam in front was supported with a out stone beam in front was supported with a out stone beam resting on two pillars. The displaced stones over steining were reset. All round the well gravel was spread. A screen wall was put up in front to prevent cattle from getting inside. Except silt elearance the work was completed.	670	. 206	•

Madanapalli Siddhavattam Cuddapah Siddhavattam Kurnool		Place. Sompalli Joti Lushpagiri Vontimitsa Kurnool	ž <u>8 </u>	Sompalli temple Hirrd Agastyeevara temple Vigneevara temple. Pushpagiri temples Ködandarana temple. Tomb of Abdul Wahab Khan,	Third Circle—cond. Renewing cut stones wherever necessary. Afresh estimate is under preparation for further repairs ordered by the Archeological Superintendent. In addition to the cleaning of the pillars of the temple shrines, mandapa, etc., the sand in the courtyard was also removed, to some extent. The work is ordered by the Archeological Superintendent to be stopped and the idols sent to Madras Museum. Renewing the terracing, plastering and pointing with cement compound wall with dry stone, renewing the flooring, etc., done during the year. The work is in progress. Compound wall with coping was done. The work is in progress. Compound wall with coping was done. Special repairs.—Renewing the masonry. Paroviding the iron work with light buff colour was done. Special repairs.—Renewing the masonry. Providing fixed iron grated partitions with doors in the arched openings and wooden gates in the cher openings. Closing the existing pathway to the river with a stone wall. Rooting out vegetation in the masonry. Providing fixed iron grated partitions with doors in the arched openings. Closing the existing pathway to the river with a stone wall. Acquisition of houses close by and demolishing of the same-for providing a pathway to the river.	Amount anotioned. 17 17 375 376 20 20 20	Actual expenditure. R8. A. P. 14 0 0 190 0 0 355 0 0 25 0 0 25 0 0 3,528 6 2	Remarks. Work completed and completion report sant. Completion report awaited from the Sub-Divisional Officer. Ordinary repairs. Ordinary repairs. The Muhammadan Religious Endowment Society, Kurnool, pays a contribution of Rs. 50 under G.O. No. 1259, Public, dated 22nd November 1911.
. Kottayam	•	Tellicherry		Fort	Removing vegetation from walls. Killing roots and making up laterite masonry where roots have been dug out from the	100	100 0	0 Work completed.

Statement of expenditure on conservation work carried out during the year 1915-16-cont.

Number.	District.	Taluk.	, <u>1</u>	Place.		Name of mo	monument.		Description of repairs done during 1915-16.	Amount sanctioned.	Actual expenditure.	Remarks.
1	and the state of t			and the second s			A	Fourth	Fourth Circle—cont.		* :	
45	Malabar	. Palghat	:	Palghat	:	Fort	•	. Rem	Removing vegetation from Fort walls and most all round and pointing with	us. 490	RS. A. P.	P. Work completed.
: · ·	Do	Wynaad	:	Sultan's Battery	ery	Jain temple	:	co Clea	here 1 ns and e app	10	10 0 0	Do.
4,	South Canara .	Käsargöd	:	Bekal	:	Fort	:	Reb	clearing vegetation. Rebuilding the colalysed portions and ramnart walls and clearance of wild	1,000	0 666	Do.
4.6	Do.	Uppinangadi	gadi	Jamalabād	:	Rock Fort		Clea	rem	140	141 0 (0 Do.
94	Salem	Salem	•	Taramangalam	:	Siva temple		Spec	wants of the arota rote. Special repairs to the roof, the floor and stone walls.	:	93 () (0 Represents 1/6 of the outlay incur- red on the estimate for Rs. 620 written back to deposit contri-
47	Do	. Attur .	:	Attur	:	Fort		Cles	Clearing prickly-pear and vegetation and	340	356 0	bution. 0 · Completed.
8	Do	. Tiruchengodu	godu	Sankaridrug	:	Do.		Ord	other ordinary repairs. Ordinary repairs such as clearing prickly-	200	0 997	6 · Do.
0.00	Do Trichinonoly	Krishnagiri Namakkal	:: -	Krishnagiri Namakkal	•	Do	damele	Ord	pear and vegetation, etc. Ordinary repairs	300	291 n 157 0	0 Do.
343	Do.	Do.	: :	Do.	::	Do.	ordima	S. S.	Special repairs	200	00	
7 mg	Do. Coimbatore .	. Avanashi		Avanashi	• •	Siva temple	::	Egen	Urdinary repairs Renoving vegetation, brick bats, rubbish, etc., repairing the yards in the sides of	120	0	0 Work completed A further expen- diture of Rs. 100 was incurred on
4	Do.	. Brode .	:	Vijayamangalam	lam .	Jain (emple	:	R R Refiger	mandapa and constructing side walls for staircase in gopman, etc. [Repairs special]. Removing broken covering stones and replacing them by fresh ones; removing the cracked terracing and renewing the stone walls just at the sides rebuilding the stone walls just at the sides	167	167 0	the repairs and it was debited against the contribution received from the Devastanam committee. Work completed.
න ය ය	Nilgiris	Coonoor	::	Hulikaldrug Banagudi Shola of Jakkaneri.	ola of	Fort Group of	dolmens		of doorway with old stones and removing vegetations, etc. [Repairs special.] Clearing jungle, etc. [Repairs annual] Clearing ferns and fallen leaves and levelling atth. [Repairs appeal.]	26 203	24 0 16 0 20 0	Do. Do. Do. Work in progress
22 kg	Do	Do Ootacamund	nd	Batlada Acheni Melkundah	::	Sculptured dolmens. 10. cromleohs	dolmens eromieohs	•		ங்க		

Statement of expenditure on Conservation work carried out during the year 1915-16-cont.

Madras	Number.	Distriot.		Taluk.		Place.	Name of monument.		Description of repairs done, during 1915–16.	Amount sanctioned.	Actual expenditure.	Remarks.
Madras M					-				Fifth Oircle.			
Do. Do. Do. Do. Old Abadras Annual regains Do. D	60		:	Madras		Madras		7.4	: :	ns. 40	25.	Work completed.
Do. Do. Do. Do. Do. Tonh of Messre. Annual repairs Do.	09		:		:	:	Old town Madras,	<u>-</u>	Special repairs	230 100 30 0	9 4 11	Do. The excess is due to the write-back of the amount realised by the sale of dismantled materials from the work to the Provincial Rev-
Chingleput Chingleput Ashabaliputam Repairs Chingleput Do Plantution of easus Panding and watering. Do Do Plantution of easus Plantupam Repairs Plantupam Bo Plantupam Repairs	61		:	`D₀.	:	:	Tomb of Elihu Yale soseph Hym		97/Q3	45	9	enne.
Do. Do. Do. Planking and watering the casuarina planta- Fire Raths Fire	62		:				Repairs to			180	ಣ	Work completed.
Do. Do. Do. Do. Do. Eive Raths Do. Five Raths Five Raths Five Raths Do.	63		:		:		Planta rina Rath		neeping paths that whering. Planting and watering the casuarina plantation.	200	0	Completed. Expenditure to end of 1914-15Rs. 368-5-3.
Do. Do. Do. Do. Chingleput Remains Repairs to reventment on either side and regarding of a portion of the same. Seal vankuppan Pive Haths Repairs to reventment on either side and regarding of a portion of the same. Seal vankuppan Pive Haths Repairs to constructing a retaining wall on east and west failed of Varaflamandapa. Pive Haths Repairs to the archaeological Remains. Pive Haths	64		:	Do	:				Formation of a Road to Five Raths-Improve-	026		In progress.
Do. Do. <td>65</td> <td></td> <td>:</td> <td></td> <td>:</td> <td></td> <td>Shore</td> <td>:</td> <td>Repairs. Repairs to revetment on either side and</td> <td>009</td> <td>10</td> <td>1)0</td>	65		:		:		Shore	:	Repairs. Repairs to revetment on either side and	009	10	1)0
Do Do Jo Varāhā Mandapa Constructing a retaining wall on east and left left left left left left left left	99		:	Do.	:				Watering casuarina plants	96	7 7	Completed.
Do Do Balvankuppam Archæological Repairs to the archaeological Remains. Benains. Remains. Benains. Chingleput "Ther Mahal" Annual repairs—whitewashing Ralatur Manimangalam Old temple with Plastering, terracing, etc., special repairs Tho Munkudimisvara Plastering, etc., special repairs In progress. Benains. Bo Do Munkudimisvara Plastering, etc., special repairs In progress. Benains Munkudimisvara Plastering, etc., special repairs In progress	19		:	Do.	:				Constructing a retaining wall on east and	160	œ	Completed. Expenditure to end of
Do Do Chingleput "Ther Mahal" Annual repairs—whitewashing 285 221 14 0 G 72 14 0 To 15 0 To	α Σ		:						Repairs to the archaeological Remains. Excavation to see if there are any more hidden monuments.	200	12	Completed. Expenditure to end of 1914-15 is Ra. 90-5-0.
Do Do Kalattur Munkudimisvara ance in the Reformatory school—Removing the blocking masonry. Do Do Kalattur Munkudimisvara temple.	69		:				. Ther	:	Annual repairs—whitewashing Special repairs—Restoring the archways in the 2nd stoley to their original appear-	2 85 80	41.	Completed.
Do Do Kalattur Munkudimisvara Plastering, etc., special repairs 150 123 0 0 Ir	01		:				Old temple	with	ance in the Reformatory school—Removing the blocking masonry. Plastering, terracing, etc., special repairs.	730	259 13 10	
	וג		:			:		i	Plastering, etc., special repairs	150	o	T

Chingleput Do Do Tinnevelly Do Tinnevelly To. Tinnevelly Tinnevelly	Conjeeveram Do Do Tivanangalam Srivaikuntam Srivaikuntam Do Ambasamudram Tangasseri Ambasamudram	::::: ::::::::::::::::::::::::::::::::	Conjeeveram Do Do Falni Agaram Rarisaluduman- galam. Tangasseri Do	Kailasanatha tem plo. Mathangesvara temple. Airavatesvara temple. Vaikuntaperumal temple. Idumbamalai. Koilpatti temple. Prehistorio kewains Vishnu temple. Kanagasabai temple Tangasseri Do	Eth Oircle cont. Special repairs Pointing	Amount sanctioned. Bas. 690 100 55 350 110 114 778 200 200 200 200	Actual expenditure. RB. A. F. 250 8 1 77 12 4 8 4 7 63 6 11 11 0 0 11 0 0 11 0 0 200 0 0 200 0 0 48 0 0 48 0 0	Completed with savings. Do. In progress. Completed. Lo. Lo. Lo. Lo. Lo. Lo. Lo. L
Trichinopoly	Perambalur	:	Valikondapuram	Valisvara temple	Walls. Minus outlay due to the transfer of 170 sq. ft. cut stone to extending and improving	: ^	- 35 7 0	∌
:	Do.	:	Ranjangudi	Ranjangudi fort	the Folice station, Perambalur. Removing prickly-pear, roots, etc., and burning them. Removing and repacking the rough stone retaining wall. Repairing mugils, outling and removing trees in the Which,	236	271 4 6	Divisional officer. Do. do.

Statement of expenditure on Conservation work carried out during the year 1915-16-cont.

during 1915-16. Amount Actual Remarks.		nortar. Pointing 425 440 15 11 In progress.	compound wall all 20 10 12 0 Do.		, sundry repairs and 300 295 0 0 Completed.	g vegetation 15 15 0 0 Do. g vegetation. 255 255 0 0 Do. epairs to walls, 330 330 0 0 Do.	watchman. Annual 60 60 0 Do.	ss have been got 100 100 0 0 In progress.	dam in the Fort 220 217 0 0 Completed. rth to allow free epairs.	o the roof of the 120 120 0 0 Do.	mandapa—Man- ete and cutstone 120 70 0 0 Completed. Amount of contribu- tion received is Rs. 50.	ish removed and 80 28 0 0 Completed.	ion charges for 6 0 0 Do.
monament. Description of repairs done during 1915-16.	Sixth Circle—cont.	ery Underpining with broken mortar. Pointing with mortar, painting whitelead and filling in with sand.	carvings Whitewashing the compound wall all round. Pointing and repainting the notice board.	Seventh Oirole.	vegetation nance of	in the	Maintenance of a watchman. Ann repairs.	rock-out Annual repairs.—Iron gates have been got for fixing.	entrance Renewing an old masoury dam in the Fort moat and removing earth to allow free flow of water. Special repairs.	nple and Special repairs.—Repairs to the roof of the mandapa in front of Garbagraha.	mple Special repairs.—Central mandapa—Mandapa roofed with concrete and cutstone beams.	ine Ordinary repairs Rubbish removed fallen pillar rebuilt.	emple Special repairs. Supervision charges for
Place. Nume of mon		nopoly Preston's battery	Rook-out		ragiri Mahal	purum F	Delhi gate	Mahendrawadi Monolithic temple.	o Ditch at the entrance of Fort.	Siyyamangalam Rook-cut temple and soulpture.	Padavedu Hanuman temple	Kuranganimuttam. Rock-cut shrine	di Cholesvara temple
Taluk.		Trichinopoly Trichinopoly	Karur Tandoni		Chendragiri Chendragiri	Vellore Vellore Do.	Walajapet Aroot	Do Maher	Vellore Vellore	Wandiwash	Polur	Cheyyar	Chittoor Melpadi
District.		Trichinopoly	. Do		Chittoor	Do North Areot Do	Do	Do	Do. :	Do.	ъ.	Do	Chittoor
Number.		87	88		68	90 91 92	88	7 6	95	96	6	86	66

Statement of expenditure on Conservation work carried out during the year 1915-16-cont.

Remarks.		In progress.	Gormioted		Contribution amount received Rs. 166.	Completed	Do.	Do.	Do.
Actual expenditure.		2,517 0 0	. 89	• •	94 0 11	490 0 0	125 0 0	1,347 0 0	1,149 0 0
Amount sanctioned.	-	ns. 2,500	, and a second	100		490	150	1,450	1,150
Description of repairs done during 1915-16.	Seventh Circle—cont.	Special regairs.—Packing old stones, revetwall. Forming new stone steps from rampart to Venkstaramana temple and packing revetments at sides of the steps. Removing the old terrace and repairing the terrace with new brick jelly in mortar and plastering the same with coloured mortar of the original mandapas II and	Improving the roads of Rajagiri hills. Rebuilding the fallen parapet wall of the eastern flight of steps from foot to the top of Krishnagiri hills. Removing and rooting out prickly-pears, bushes in different buildings in the Fort.	for the Ginges Fort; cutting bushes for the building and cleaning pathways. Special repairs—Widening the drainage channel in the Doct of Amin the profile.	completely. Special reports.—Rectification of drainages on the tower carried out during the year	at the instance of the Collector. Special repairs.—The fallen portion of the inner e-contempart wall and rampart wall west of the front tower of the great	temple were renewed. Annual repairs.—The vegetation was removed and the pathway around was		concrete work. Inside was plastered and whitewashed. Rotten door shutters renewed: Inscriptions were rewritten. Special repairs.—The arched openings in front were fitted with wire nettings. Glazed familights and chicks were provided for the retrangular bays between pillars.
Name of monument.	Seventh	Gingee fortresses		Fort St. David	Sarangapani temple	Inner escarpment wall of the Sivaganga Little Fort.	Sivaganga Little Fort.	Schwartz church	Providing glazed fan- lights and chicks in the Statue hall in the Taniore Palace.
Place,		Gingee		Devanampatnam	Kumbakōnam	Tanjore			Do. :
Taluk.		Ging ee		Cuddalore	Китракопат	Lanjore	: O		
District.		South Areet		Do.	Tanjore		Do	Po	Do. ::
Number.		100		101	102	103	104	105	106

APPENDIX D (2).

Statement of expenditure on Conservation work carried out in Coorg during the year 1915-16.

Вепатке.		Annual repairs.—A sweeper has also been employed throughout the year to look after the surroundings of the buildings. Work completed.	Annual repairs.—A watchman has been employed throughout the year to look after the building and the furniture. Work completed.	Original work.—Work completed.
Actual expenditure.	B.8. A. P.	168 12 9	53 5 1 3	253 6 11
Amount sanctioned.	BBS.	7 270	500	270
Description of repairs done.	Fort.—Repairing and painting the masonry elephants and horses, olearing rank vege-	tation, blinding over roads inside the fort and approach road with good gravel and obering and repairing the well, draining oulverts and latinies, etc. Raja's seat.—Repairs to floor, plaster base- ment, and leaks to roof, etc.	White-washing, tarring and painting the roof with solignum, varnishing the furniture, dismantling the roof timber, rc-tiling and ridging with ridge tiles, repairs to leaks in roof, doors and windows, floor and plackers.	An a provided to bring the water from a stream close by to the palace, as much difficulty is felt by officers touring.
Name of monument.	Fort and Raja's seat		Nalknad Palace	.:
Place.	Mercara		Nalknad	Do :
Taluk.	Mercara		Padi Nalknad	Do
ję.	•		· ·	:
District.	Coorg		Do	Do
Number.	-		63	က



THE ORIGIN OF THE TYPICAL HINDU TEMPLE OF SOUTHERN INDIA.

In spite of the variety of plan and design employed in the different types of Hindu temples met with in Southern India, it is perfectly safe to assert that all of these various styles are generally speaking, nothing more or less than developments of former types of Buddhist buildings. The same remarks apply to the various styles of Hindu temples found in Northern India, but in the South we have so many existing primitive shrines belonging to the pre-Buddhist period that it seems worth while to examine these before accepting the assertion made above in case the latter may have had any possible influence in determining the planning of some of the types of Hindu temples which succeeded them. The apsidalended temple; the pyramidal storeyed temple; the waggon-headed roof; and the circular shrine chamber found in some temples on the West Coast, are all so obviously Buddhist in origin that they need not be discussed here. However, the commonest type of Hindu temple found in Southern India, is the typical village temple. A small structure as a rule, with a tomb-like cell enshrining the image of the local god or goddess as the case may be. Like the other types of Hindu temples found in Southern India, at first glance, this style of temple too, appears from its outward appearance to be purely Buddhist in origin but the somewhat extraordinary similarity between the planning and construction of the shrine chamber of this type of temple and those set up by the ancient Dravidians in pre-Buddhist times may indicate that the plan at least, has an origin anterior to the advent of Buddhism in Southern India. Therefore, if we are to trace the origin of the typical South Indian temple to a period anterior to the advent of Buddhism in the South we must examine the existing remains of the so-called Pre-historic period. Monuments of this period cannot be said to be of any architectural value, but they are interesting as illustrating from what humble beginnings the noble art of architecture has been evolved. The megalithic remains of the Pre-historic period are mostly sepulchral, and in order to understand their true value in connection with our present purpose, some knowledge of the religion and manners and customs of the people who built them is necessary before we proceed further.

In Pre-historic, as in modern India, various methods for the disposal of the dead were adopted. The men of Palaeolithic times probably abandoned their dead in the forests, as the Oritae of Gedrosia (Makrān) continued to do in the days of Alexander the Great. In the Neolithic Age burial was probably the rule, and it seems certain that the practice of burial is older than that of cremation.

Megalithic tombs in great variety of form abound in the Deccan and Southern India. They have sometimes been found to contain both stone and iron implements, showing that in India, these two periods overlap, and they are evidently of very various ages, some being truly Pre-historic, while others may be described as comparatively modern.

From the style of the construction of these sepulchral monuments and the nature of the contents discovered in them,* it is clear that in ancient India, ancestor-worship, or more broadly, the cult of the dead, formed the staple of the religious belief of the original inhabitants in early times. The religion of the Dravidians, however, also included a phallic cult as well as the worship of snakes and trees, which things were at first repugnant to the Aryans, though later on when the latter amalgamated with the earlier inhabitants, they were admitted under the worship of Siva.

This cult of the dead led to the custom of depositing in the tomb the weapons and implements, tenement and gear, enjoyed in life, as the dead were supposed to require the same kind of food and equipment as when living, and to molest the survivors unless they obtained it. Those who caused sorrow and trouble in life were after death supposed to be the cause of further unhappiness, and as such they had to be propitiated with gifts which they would have appreciated when alive. They had to be supplied with the weapons, the cooking pots, the water jars, the ornaments, and the implements which they used during life. Periodically solemn festivals were held, and a portion of the viands was solemnly set apart for the departed. This feeling of awe in which the spirit of the dead was held, led to the custom of providing a material abode for the soul or ghost. The survivors believing that the ghostly ogre, being so well provided for, would abstain from haunting or molesting them.

In Southern India, these special soul houses were generally set up in the form of large or small dolmens, usually consisting of one large flat slab of stone supported by three upright slabs set on end or on edge so as to form a small chamber with one side open to serve as an entrance. Plate I Fig. (a) illustrates a typical specimen of a large Indian dolmen. This quaint monument stands on the top of a small granite hill at Kalyandrug in the Anantapur district of the Madras Presidency. It is of the usual rectangular shape, formed of three huge upright granite slabs for the three sides and a fourth for the roof; the front or north side being open. The interior of the dolmen measures 6 feet 7 inches in length, 4 feet 4 inches in width and is 5 feet 8 inches in height. The slab on the east side is 6 feet 7 inches in length, 5 feet 8 inches in height and 5 inches thick. The slab on the west side is 7 feet in length, 5 feet 8 inches in height and 5 inches thick; and the back or south slab is 5 feet 9 inches in length, 5 feet 8 inches in height and 5 inches in thickness. The roof slab measures 9 feet 3 inches by 11 feet and is 4 inches thick. The floor has been slightly

^{* (}See Arnual Report of Archæological Department, Madras, for 1913-14 and 1914-15.)

raised above the natural sheet rock on which the monument stands, by inserting a huge paving slab 4 inches in thickness. Since the side slabs rest on the natural rock, and are kept in position mainly by their own weight and the roof slab above them, the paving stone is necessary in order to resist the tendency of the side walls to fall in. These old dolmens are usually found intermingled with cairns and kistvaens of the usual type and appear to have been erected as special abodes for the ghosts of the departed and also as receptacles for votive offerings made by the survivors to propitiate the spirits of the dead.

At a later period, dolmens of this kind were sometimes converted into hero-shrines dedicated to some local chief or warrior who died, or was slain in battle and whose wife or wives committed sati on his pyre. Plate I Fig. (b) illustrates one of these sculptured dolmens also discovered at Kalyandrug, in which neighbourhood both types of dolmens are common. The two hero-shrines illustrated in Plate II were found in the same district. The back slab of the one depicted in Fig. (a) bears a crude representation of three warriors with drawn swords carved in bas-relief. It is situated about half a mile to the west of the hamlet of Mudigallu and three miles from Kalyandrug. Fig. (b) of the same Plate illustrates another hero-shrine at Rayadrug in the same district. The bas-relief represents two warriors with drawn swords. In this case, it is carved on a separate slab of stone inserted in the dolmen and not carved on the back slab as we usually find. As a rule, these hero-shrines face the east. There appears to be little doubt that the large slabs of stone used in constructing these hero-shrines, were taken from some of the old dolmens or ruined kistvaens which abound in this district. The style of the sculptures indicates that the figures depicted represent petty chiefs or feudal barons of the Vijayanagar period and in all probability, they are not earlier than the 15th century A.D., although it is possible that the stone slabs themselves may have originally belonged to dolmens or kistvaens of the Prehistoric period. The local villagers possess no reliable information concerning the history of these hero-shrines. They appear to respect them, and in some cases offerings and vowe are still made at these curious shrines which they generally speak of as "gods houses" and believe that some local deity does actually reside in them.

Critical observers, like the late Sir Alfred C. Lyall, attest innumerable examples of the gradual elevations into gods of human beings, the process even beginning during their lifetime. A man wins local fame as an ascetic with abnormal powers, or a wife, because Alcestis-like she sacrificed herself for her husband and immolated herself on his pyre. Miracles occur at their shrines, and the surviving relations who guard them wax rich off the offerings brought. In the course of a few years as the recollection of the man's personality becomes misty, his origin grows mysterious, his career takes a legendary hue, his birth and death were both supernatural; in the next generation the names of the elder gods get introduced into the story, and so the marvellous tradition works itself into a myth, until nothing but a personal incarnation can account for such a series of prodigies. The man was an Avatar of Vishnu or Siva; his supreme apotheosis is now complete and the Brahmans feel warranted in providing for him a niche in the orthodox pantheon. No doubt these departed warriors now under consideration, were elevated to the rank of demi-gods in much the same manner as that cited above.

Sculptured dolmens of this class and period are also common in the Nilgiri district, and no doubt their origin and history are much the same in both cases.*

At Kambadūru, a village on the southern frontier of the Kalyandrug taluk, and 18 miles from the town of that name, there are three very interesting old dolmens which have been set up as Siva shrines, and it is possible that we have here the prototype of the so-called Dravidian or ordinary South Indian type of Hindu temple. In Plate III Fig. (a), we have two examples of these primitive Siva shrines standing close together, the one in the foreground is much the same in size and style as the large dolmen shown in Plate I Fig. (a) only it has been converted into a Siva temple by the introduction of a stone linga surrounded by a low flat yoni pedestal of early type, and a drainage hole for the exit of holy water poured over the linga, has been cut through the stone slab forming the north wall of the shrine as may be seen in Plate IV Fig. (a). At a short distance to the south-west of this shrine we have no longer a primitive dolmen, but a carefully built temple enshrining a tall stone linga on a yoni pedestal of the usual type. The three side walls and the roof are not built of roughly hewn slabs as we find in the earlier example, but consist of four large slabs of stone carefully cut and dressed and accurately fitted at the angles. The side walls rest on a moulded plinth about one foot in height and are not planted in the ground like the wall slabs of a dolmen. The mouldings of the stone plinth are very simple, consisting of two rows of projecting flat bands or fillets. Lying in front of the shrine is a large neatly cut paving slab for the interior. This stone appears to have been torn up and thrown outside by treasure-seekers at a later date. Both of these shrines face due east and are illustrated in Plate III Fig. (a), standing close together.

At a short distance to the south-east of these two shrines is the dolmen temple illustrated in Plate III Fig. (b) and Plate IV (b). This is also a Siva shrine containing a stone lings and you stand like the others just mentioned. The construction of the shrine chamber is similar to the dolmen temple shown in Plate III Fig. (a) only here the shrine chamber

has been provided with a hall or mandapa in front connected with the shrine by a small passage, the entire structure being roofed with three roughly hewn flat slabs of granite. Like the other two shrines just described, it faces due east. The plan of the building is the usual kind for small Hindu temples in the so-called Dravidian style.* It only requires the usual dome-shaped brick and plaster ornament known as the "Stūpi" in Southern India, above the flat roof over the sanctum, to complete its resemblance to any ordinary village temple of the usual type, such as those shown in Plate V Figs. (a) and (b).

The term "Stūpi" would appear to be a corruption of the Sanskrit word "Stūpa," since both words are used to designate the same type of structure. With the Buddhists, the stūpa was a dome-shaped structure which was a development of the low sepulchral tumulus or mound of earth and stones†, in which baked bricks were substituted for earth with a view to durability. The purpose for which they were erected by the Buddhists was to serve as monuments enclosing relics of Buddha or of Buddhist saints, which were placed in a stone coffer. Some, however, contained no relics, but were only commemorative of important events connected with the history of Buddha. In Northern India, the name tope is generally applied to stūpas and in Ceylon stūpas are usually called dhagobas (from "dhata" a relic and "garbbha" a receptacle). According to General Cunningham, the word tope is derived from Afghanistan, where it is used to designate any solid mound of masonry. He is of opinion that the word tope is the same as the Pali "thupo" and the Sanskrit "stūpa," a mound or tumulus, both of which terms are of constant use in the Buddhist books. Stūpa or tope, is therefore a name common to each kind of tumulus, whether it be the solid structure dedicated to the Supreme Being, or the massive mound erected over the relics of Buddha, or of one of his eminent followers.

From several passages in the Pali Buddhistical Annals, it would appear that stupas were in existence prior to the advent of Buddha; and that these were objects of much reverence to Buddha himself particularly inculcated the maintenance of these ancient tombs, and the continuance of the accustomed offerings of worship. But this was in all probability only a politic accommodation of his own doctrines to the existing belief of the people, adopted for the purpose of ensuring a more ready assent to his own views. Buddha acknowledged the noly 'Munnis Kakutsanda'' (or Krakuchanda), "Kanaka," and "Kāsyapa," as his immediate predecessors. They were probably heroes or saints, who had obtained the respect of their fellow-countrymen during life, and their reverence after death. Stūpas had been erected over their relics in the neighbourhood of Kapila and of Benares, and their worship was too firmly established to be attacked with any chance of success. Buddha therefore artfully engrafted them into his own system as the "Buddhas of a former age." It appears also that stūpas had been erected over the remains of Supreme Monarchs prior to Buddha's advent for Buddha himself particularly informs his disciple Ananda that, over the remains of a "Chakravarti Raja, they built the stūpa at a spot where four principal roads meet." It is clear therefore, that the stūpa or tumulus was the common form of tomb at It is clear therefore, that the stupa or tumulus was the common form of tomb at that period. In fact the tope or stupa, as the name implies, is nothing more or less than a regularly-built, dome-shaped pile of masonry, which was undoubtedly the oldest form of funeral memento. But, although the original object of the stupa was to cover the remains of the Great, or to enshrine the relics of the holy, yet, in a short time, other stupas, or me-morial monuments were erected on spots rendered famous by the leading events of Buddha's life. These holy places rapidly increased in number, until there was scarcely a large city in India, from Kabul to Orissa, and from Nepal to Ceylon which did not possess a monument illustrative of some act of the Great Teacher. For this end, the doctrine of transmigration was highly accommodating; for although the mortal pilgrimage of Buddha was confined to the valley of the Ganges, yet there was no part of India which he might not have visited in some former existence; and in this manner, indeed, he is said to have been in Ceylon. Thus there were three kinds of Buddhist stūpas:—

- (1) The "Dedicatory", which were consecrated to the Supreme Being.
 (2) The strictly "Funeral", which contained the ashes of the dead.
 (3) The "Memorial", which were erected upon celebrated spots.
- It is improbable that any deposit would have been placed in the "Dedicatory Stūpas" which were probably consecrated to the Supreme Being, the invisible "Adi-Buddha". In the stūpas dedicated to the celestial "Buddha", the invisible Being who pervaded all space, ro deposit was made, but the Divine Spirit, who is "Light" was supposed to occupy the interior, and was sometimes typified on the outside by a pair of eyes, placed on each of the four sides either of the base, or the crown of the edifice. Such is the great stūpa of Shambu Näth near Katmandu in Nepal dedicated to the "Self-Existent" or Supreme Being, in which the eyes are placed on the four sides of the "tee" or upper portion of the building as may be seen in Plate VI.

The earliest stūpas were very low in proportion to their diameter. Thus the oldest known example, the brick stūpa or relic mound at Piprahwa, on the Nepal frontier, which was explored seventeen years ago, and has, with probability, been assigned to 450 B.C., stands only about 22 feet high, with a diameter at the base of 116 feet. As

^{*} See Plate IV Fig. (b).

† See illustrated report on the excavation of certain cairns in the Kurnool district in Part II of Annual Report, Southern Circle, for 1914-15.

time went on the relative height increased. Thus the great stūpa at Sanchi in Central India, erected some 200 years later, is 54 feet high, while the basal diameter of the dome is 106 feet. The proportional height here is just about half, while at Piprahwa, it is less than one-fifth. In other words, the stūpa shows a tendency in course of time to assume the shape of a dome-shaped tower. On top of the dome was a box-like structure surmounted by one or more umbrellas (the Indian emblem of sovereignty). This structure is usually called the "tee" (a Burmese word). The tee has disappeared from all the Indian stūpas, but its form can be seen from the stūpas surviving in Ceylon and Nepal,* as well as from stone models and sculptural representations preserved in great numbers in India.

The stupa became to the early Buddhist "the" religious edifice. In the earliest sculptures we constantly find representations of it being adored by men, celestial beings and even animals. It was also the sacred object always set up for worship in all the temples of early Buddhism in India

When Buddhist pilgrims visited any of the famous sites connected with the life of their great teacher, it was their invariable custom to make some offering, no matter how poor, to the shrine, and at the same time set up some memorial of their visit. These offerings consisted of money, precious stones, vessels and costly cloths by the rich, and of fruit and flowers by the poor. The memorials generally took the form of stūpas, and temples of all sizes by the wealthy, and of small model stūpas, or inscribed tablets by the poor.

There is a great variety in the shape of these votive stūpas, from the low and almost bare hemisphere of the time of Asoka to the tall ornamental spire surmounting the mediæval dome with its elaborately carved basement. A striking change in the mediæval stūpa, is the introduction of figure sculpture. Only ordinary mortals are sculptured in the earlier stūpas, while Buddha never appears. Now he is even the object of worship, his image being placed in a niche in front of the stūpa itself. This is well exemplified in Plate VI, where a great number of mediæval votive stūpas are shown in the foreground of the photograph and their resemblance to the "stūpi" of the so-called Dravidian Hindu temple may be observed.

The Buddhists were the first builders and carvers of stone in India, beginning in the reign of Asoka, the great Emperor (264-227 B.C.), whose rule extended practically over the whole peninsula. Originally au adherent of the Brahman religion, he became a convert to the doctrine of Buddha and devoted himself to promoting its interests, during the remainder of his life. It is only on Buddhist monuments that we find the earliest representations of Hindu deities. Thus Lākshmi, the Hindu goddess of Fortune, worshipped by two elephants pouring water over her, appears on Buddhist sculptures from the second century B.C. onwards. But the oldest remains of independent Hindu art, either sculptural or architectural, only date from several centuries after the beginning of our era. These considerations in themselves justify the presumption that Hindu architecture is derived from the older art of the Buddhists. This presumption is borne out by the fact that the earliest extant Hindu examples are, practically identical in form and on plan with the latest Puddhist specimens differing from the latter only in having the image of a Hindu deity, instead of one of Buddha, placed in the shrine.

The whole surface of India is covered with Hindu temples, the vast majority of which are quite modern or comparatively so. The number of ancient temples is small, chiefly, perhaps in consequence of the destructive religious fury of the Muhammadans, who invaded India from 1000 A.D. onwards. The oldest examples date from the 7th century of our era, and the best specimens are to be met with between that date and the 15th century. In surveying these ancient monuments we can clearly distinguish two styles, each or which shows a definite type from the beginning. The Northern or Indo-Aryan style of Hindu architecture is found only north of the tropic of Cancer, excepting only the eastern and western extremities of its territory, which come down to the 20th degree. The Southern or so-called Dravidian style, on the other hand, is found only within the tropics, or south of the 23rd degree of the northern latitude. The Indo-Aryan Hindu temple is a development of the Buddhist temple.† The origin of the typical Southern style of Hindu temple is not quite so clear. It would appear however, that the usual domeshaped brick and plaster ornament set up over the roof of the shrine chamber of South Indian village temples, known as the "stūpi" is nothing more or less than a conventionalised model of a mediæval Buddhist stūpa, erected purely as an architectural ornament denoting the position of the image enshrined within the building. It should be remembered that the "stūpi" is purely ornamental, as it serves no useful purpose in admitting light or ventilation into the shrine chamber below which is provided with a flat roof, usually composed of massive slabs of granite, like the roof over a dolmen or a

^{*(}See Plate VI).

† This fact was clearly demonstrated by Professor A. A. Macdonell, in his paper on "Buddhist and Hindu architecture", read before the Royal Society of Arts in 1909. It is also fully explained and illustrated in my own monograph on "The Influence of the Umbrella on Indian Architecture" published as No. 122, April 1913 of "the Journal of Indian Art and Industry."

cell-tomb. There is no communication between the interior of the shrine chamber and the " $st\bar{u}pi$ " above. The only light which finds its way into the interior of the shrine chamber, is by means of the front entrance, consequently, the interior is generally as dark and gloomy as the interior of a cell-tomb

The Buddhist stūna was generally surrounded by a massive stone railing, with gates on four sides, enclosing a procession path for circumambulation. Provision of a similar closed procession path or passage around the shrine chamber, is quite a common feature in Hindu temples in Southern India. The two temples shown in Plate V, Figures (a) and (b), are both provided with circumambulatory passages around their shrine chambers. These passages cannot be seen from outside as they are hidden by the outer walls of the building and the flat roof over the passage itself. Owing to the lack of windows in the cuter wall, it is needless to say, that the interior of the passage is in utter darkness. I venture to think, that this feature too, is an idea borrowed from the procession path of the Buddhist stūpa.

Like the Med aval Buddhist stūpa, the Hindu "stūpi" is usually built of brick and plaster, sometimes as a solid mass of brickwork, but generally the domed portion is hollow or partly hollow, in order to save unnecessary expenditure on brickwork and to relieve the weight on the flat roof below.

In Plate VII, Figure (a), we have a typical specimen of a stone model of a late Buddhist stūpa discovered on the north-western frontier of India, anciently known as Gandhāra. The best productions of the Gandhāra Indo-Hellenistic school may be dated from the first three centuries of the Christian era. The material of the sculptured model is a blue clay-slate, also described as hornblende schist. The stone was finished with a coating of fine plaster, like the rock-cut sculptures of Ajantā and many other localities in India and Ceylon, and the effect was usually heightened by the free use of colour and gilding, traces of which are still occasionally discernible. Traces of plaster may be discerned in the example shown here now under consideration. It will be noted that the dome-shaped drum rests on a square basement of two storeys, each with a boldly cut projecting cornice of Corinthian appearance supported on the under side with a row of modillions. The four corners of the lower basement together with the plinth of each face of the structure, is ornamented with figures of conventional lions and elephants. Above the plinth are panels containing bas-relief sculpture illustrating scenes from the life history of Buddha. The circular dome-shaped drum, was originally decorated on each of its four sides, with a small carved plaque surmounted by a trefoil arch containing a little panel filled with bas-relief figures representing Buddha in one of his conventional attitudes, or else figures of Buddhist Saints. The crown of the dome is ornamented with a pretty lotus-petal design. Above this is the tee, no longer a square box-like structure as we find in the earlier stūpas, but an umbrella-like ornament decorated on the underside with a lotus-petal design supported on a sturdy circular necking. This again, is crowned by four superimposed honour-conferring umbrellas. This beautiful model of a late Buddhist stūpa is now in the Archæological Section of the Calcutta Museum.

Now let us compare this Buddhist stūpa with a typical specimen of a Hindu "stūpi" The mediæval example shown in Plate VII, Figure (b) will serve our purpose. This is a small Siva temple dedicated to Siva's consort Parvatı, and stands alongside of a larger temple dedicated to that deity at Kambaduru, at a short distance from the dolmen temples described above and illustrated in Plate III. The plan of the building is similar to that of the dolmen temple shown in Plate IV, Figure (b) as may be seen by a comparison with the plan given in Plate VIII. The building consists of a shrine chamber six feet square, enshrining a carved stone mage of Parvati, and is provided with a small hall or mandapa in front and faces the east. The entire building is covered with a flat roof composed of massive granite slabs like the roof over the dolmen temple shown in Plate III (b). Like the latter, the interior is quite dark, the only access for light being through the front entrance. Above the flat roof over the sanctum is the usual brick and plaster "stūpi" as may be seen in Plate VII (b). Like the Buddhist stūpa just described and illustrated in Figure (a) of the same Plate, the circular, dome-shaped drum of the Hindu "stūpi" rests on a square basement of two storeys, each having a boldly projecting cornice. The upper cornice, and the circular cornice around the lower portion of the dome, are both ornamented with a row of modillions, similar to those appearing in the Buddhist stūpa. Instead of lions and elephants, the four corners of the two storeys of the square basement, are ornamented with figures of the sacred bull Nandi, the vāhānam or vehicle of Siva. Like the dome of the stūpa, the dome of the Hindu "stūpi", is provided with four little horseshee-shaped plaques, one on each face of the dome. They are too small to contain bas-relief figures, so a stucco image is placed immediately below them. In this case, the crown of the dome is plain, but this is sometimes decorated with a lotus petal design similar to that appearing on th

trefoil as in the stupa, but has become cinquefoil. In later times this simple trefoil arch of the Buddhists, became in the hards of the Muhammadan builders an elaborate multifoil arch of many cusps or points, and formed one of the most striking features of Saracenic architecture.

The brickwork of the "stūpi" is always plastered and usually coloured, and the kalasa is gilded, or painted yellow in incitation of gold. In later time, the Buddhists decorated their stūpas with bas-relief sculpture, or painted stucco figures, representing Buddha in all his various attitudes, or with groups of figures illustrative of some important event in the life of their great teacher. In this manner, these sculptured scenes played an important part in religious instruction. The Hindus were not slow in adopting the same custom, with the result that in the course of a few centuries, the "stūpi" became so smothered in religious ornament that very little trace of the original design of a late Buddhist stūpa was left, as may be seen in the two comparatively modern examples illustrated in Plate IX, Figs. (a) and (b). Stripped of its ornaments, a ruined Hindu "stūpi" presents the same appearance as a ruined mediæval Buddhist stūpa or temple This is shown in Plate V (a). Here we have a ruined Vaishnava temple dedicated to Narasimha, the man-lion incarnation of Vishnu, situated at Peddamudiyam in the Cuddapah district. The entire building is covered by a flat stone roof of the usual type of construction. It possesses a procession path around the shrine chamber and a pillared hall in front of the shrine. The "stūpi" over the sanctum, takes the usual form of a domeshaped brick drum resting on a two storeyed basement with a modillion cornice. It is a hollow-structure, erected purely as an ornament on top of the flat roof over the sanctum. As the building possesses no windows, the interior is in almost total darkness. From the style of the carved pillars supporting the roof over the hall or mandapa, the building appears to have been built during the Vijayanagar period, and in all probability belongs to about the 15th century A.D. In Fig. (b) of the same Plate, we have another example of the same type of South Indian village temple as that just described, only in this case, the building is more ornamental and in a far b

It seems reasonable to presume that the primitive dolmen temples illustrated in Plate III, are earlier than the Parvati shrine shown in Plate VII (b). All four temples are situated in the same village, and the question naturally arises as to whether the Parvati shrine is a development of the dolmen temples illustrated in Plates III and IV. On plan, and also in roof construction, both temples are practically identical. I venture to think that the presence of the "stūpi" over the shrine chamber of the Parvati temple has been satisfactorily explained above. This ornament may be briefly described as an architectural feature representing a conventionalised model of a late Buddhist stūpa which the Hindus adopted on the decline of Buddhism in the seventh century A.D. Its purpose in Hindu temples has already been explained above. One of the most striking features about ordinary village temples of the type shown in Plate V, is the lack of proportion in the general design, which gives the body of the building with its extraordinary amount of flat roof space, the appearance of a tomb rather than a temple. Although the "stūpi" was no doubt added partly with a view to breaking up the monotony of this long flat roof line of temples in this style it still has a detached appearance, as though it had been added as an afterthought, in fact as an additional ornament that has no real connection with the general design and planning of the building.

It is probable that the Hindu "stūpi" did not exist prior to the seventh century A.D. and the question arises as to whether any other types of temples or shrines, other than Buddhist or Jaina, existed before that date, and if so, what were they like? We know that from the reign of Asoka (264-227 B.C.) down to the seventh century A.D., Buddhism was the prevailing religion of the country, but it is possible, and extremely probable, that certain tribes and castes who were not converted to Buddhism retained their own religious belief and erected primitive shrines and memorials in honour of their own special deities. Ancestor worship, phallic-worship, and Tree and Serpent worship, have survived from the earliest times down to the present day. From existing remains, preserved in great numbers throughout the Deccan and Southern India, we know that the ancient Dravidians built cell-tombs and dolmens in connection with the cult of the dead. Also that carved stone images of Nāgas or serpents, set up by those who were believers in Tree and Serpent worship, abound throughout the Deccan and Southern India and testify to the former popularity of this form of belief.* Therefore there appears to be no reason why the followers of the phallic cult should not have erected primitive little linga shrines like those illustrated in Plate III, prior to the advent of Hinduism in the seventh century, or for that matter, prior to the advent of Buddhism.

If the Parvati type of village temple described above is not a development of the dolmen shrines illustrated in Plate III, then the latter must have been copied from the former in comparatively recent times. It seems incredible, that having attained to the art of constructing a building like the Parvati temple, that any builders should revert to such

primitive means of construction as those shown in the dolmen shrines. Moreover, if the dolmen temples had been copied from the Parvati shrine then surely, some attempt would have been made to reproduce in brick and plaster, so striking a feature as the ornamental " $st\bar{u}pi$ "? The walls of ordinary modern village shrines are usually built of rubble masonry set in mud mortar, with a flat roof over the building composed of granite slabs, the entire building being plastered over and whitewashed, and some attempt is invariably made to reproduce the ornamental " $st\bar{u}pi$ " on top of the flat roof over the sanctum.

The only other explanation that can be put forward to account for these dolmen shrines is that they are not temples in the usual sense of that term, but in reality, tombs set up over the ashes of some saint or person of importance, to be accounted for in the following manner:—Among the Hindus, the Brahmans always cremate their dead, except in the case of those who have taken Sannyāst (who have resigned the world). On the second day after cremation they perform a ceremony called Asthisanchayana. This consists as the name indicates, "the gathering together of bones" from among the ashes and preserving them in new pots sealed with clay. After the final ceremonies, which extend to ten days, are over, the bones are thrown either into a sacred river, or into a large tank or well not much used by the public. The pot or urn containing the bones during the period of obsequial ceremonies is buried underground in a marshy place close to the river or tank where such ceremonies are usually performed. On the day on which the bones are finally disposed of, they are removed from the pot and consecrated by the Vedic mantras and bathed and worshipped as pitridēvas and then thrown away in the manner related above. In the case of Sannyāsins, whose bodies are not cremated but buried in a sitting posture, a raised masonry platform is sometimes, set up over the place of burial on which a tulsi plant is grown, or a stone linga is set up as though to proclaim to the world that the body buried below has assumed the sacred form of Siva-linga.* If the tomb is richly endowed and regular festivals are held so as to attract large crowds of pilgrims to the spot, the tomb in course of time develops into a flourishing temple with its numerous devotees and mythical associations. Mr. Krishna Sastri, the Epigraphical Assistant Superintendent to the Government of Madras, informs me that in fact, many great temples in Southern India, the tombs of past teachers of that line are located within the premises of the institute and are still worshipped reg

The Lingayats whose creed appears to be a revolt against orthodox Hinduism, regularly have their religious institutions built over the graves of their spiritual preceptors who are buried in a sitting posture, and when it is possible to do so, they still bury high personages in the same premises.

This practice of burying or cremating the dead and preserving their relics, sometimes in temples and sometimes in religious institutions, has taken in this land of many religions, a special spiritual turn that has influenced its mythology. Thus Siva is known as the lord of burial grounds, and wears garlands of skulls and bones instead of jewelled necklaces and ornaments like the other great deities. Mr. Krishna Sastri informs me that the word Smasānēsvara (or in Tamil Mayānathi-Mahadeva) as a name for Siva temples, is often met with in Southern India, and such temples are either actually situated near graveyards or must have been so associated with them in past ages. Consequently, it is not surprising that Siva temples and human graveyards being so closely associated with one another from times immemorial, that skulls and human bones should sometimes come to light in the The Nattukkottai Chettis of Southern India, who are renopremises of these temples. vating Siva temples of Puranic fame on a very large scale, have often found human bones and ashes at some depth below the floor on which the sacred image stands, thus indicating that the original shrine was erected over the relics of some saint or important personage.

Mr. Krishna Sastri also informs me that, epigraphical evidences as to Siva temples being actually erected on the very spot where important personages were buried are not wanting in South Indian inscriptions. He states that, there is a record of the 9th century A.D., at Solapuram in the North Arcot district, recording that the Ganga King Rājāditya, "caused to be built a temple to Isvara (Siva) on the spot where his father had been buried "† Another inscription records that at Tondamanād in the Chittoor district. was built a shrine over or near the burial ground (pallippadai) of the Chola king Aditya I. A third inscription found in the Cholesvara temple at Melpadi states that Rājārājā I at the end of the 10th century A.D., "had been pleased to build the temple of Arinjisvara as a pallippadai for the lord who died at Arrur." Thus we have sufficient evidence to show that it was not unusual in early times for Siva temples to be set up as memorials over tombs of important personages.

The fact that even at the present day, after the cremation of the body, Brahmans collect the charred bones and place them in an earthenware pot sealed with clay and bury them in the ground for some days (in a recognised burial-ground) before they are finally cast away on the waters of a sacred river, or tank, seems to indicate that at some remote period the remains of dead were usually buried and that the custom of casting the remains into a sacred tank or river is a later idea which has crept in with priestly intercession for the welfare of the dead.

The vast number of cell-tombs or kistvaens which abound throughout the Deccan and Southern India, show that in early times, the better class people disposed of their dead by collecting the bones and placing them in pots or urns, usually sealed with clay or pottery lids, which were placed in particularly massive tombs composed of large granite slabs, like those discovered at Gajjalakonda in the Kurnool district, described and illustrated in Part II of the Annual Report for this Circle for 1914-15. It was also the custom at that period, to provide the dead with the metal implements and weapons, jewellery and ornaments, and domestic utensils enjoyed during life. Thus the construction of these elaborate tombs, which sometimes took the form of a family vault containing the remains of half a dozen different people, and the provision of the implements and gear of the departed must have proved a somewhat costly undertaking for the surviving relatives, especially in times of famine or distress. Therefore, it is not surprising that, if in later times the Brahmans introduced a new and more sensible form of burial, which did away with the construction of costly tombs, and did not entail the sacrifice of household goods and chattels, that the people should be ready and willing to accept it without question.

That the practice of constructing megalithic tombs and sepulchral memorials dates back to a period anterior to the advent of Buddhism in Southern India has already been shown above. Unfortunately, nothing has been discovered in these cell-tombs or kistvaens to indicate the exact nature of the religion of the people who built them. It is possible that the dolmens may have once contained wooden or pottery images which have since decayed, as they appear to have been erected mainly as shrines of some kind, and they undoubtedly belong to the same period as the cell-tombs.

The earliest Hindu temples in Southern India are those at Mahabalipuram in the Chingleput district and which are generally known as the "Seven Pagodas." The inscriptions on these temples record that they were hewn out of the living rock by the Pallavas in the 7th century A.D., and the style of their architecture clearly shows that they are stone models of former Buddhist buildings which have been adapted to suit the requirements of Hinduism. Although some of these temples are very large and profusely sculptured outside, the shrine chamber is invariably a small tomb-like cell with a low flat roof free from all ornament and dark and gloomy within. Since we know for certain, that in Southern India, tombs have in course of time become transformed into temples, and that Siva temples were also set up over tombs as memorials to important personages in the past, it would appear that the cell-like proportions of the shrine chamber of a typical South Indian Hindu temple may be traced to the Dravidian cell-tomb or dolmen. We know that the North Indian style of temple is a development of a Buddhist stūpa or tomb, and there is no reason why the typical South Indian type of temple too, may not also be a development of a tomb, but in this case, not necessarily a Buddhist tomb, since so many older Dravidian tombs exist to serve as prototypes for the plan of such temples. Apart from the plan however, there can be no shadow of doubt that the external design and ornamentation of temples in this style, like all other types of South Indian temples, owe their origin to the older art of the Buddhists.

THE MAHENDRAGIRI TEMPLES IN THE GANJAM DISTRICT.

The Mahendragiri temples are situated on the upper portion of the famous Mahendragiri hill at a distance of 19 miles north-west of Mandasa Road railway station on the main line between Madras and Calcutta. The mountain is 4,923 feet above the sea level and is included in the Mandasa Zamindari of the Ganjām district. Originally, there were four temples but now only three are left standing, the plinth and stone doorjambs of the fourth temple alone remain. Two of these temples possess important historical inscriptions and these were copied by the Epigraphical branch of this department in the year 1896 when they were registered as Nos. 394 to 397 of the stone inscriptions collected in that year.* However, no action was taken at the time for the preservation of these temples or even for their inclusion in the Standard List of Ancient Monuments. Thanks are due to Mr. G. H. Welchman, Special Forest Officer, Parlākimedi Maliahs, for again bringing their notice to this department and suggesting their proper conservation. So in G.O. No. 321, Public, dated the 14th March 1914, these three temples were permanently included in the Standard List and I personally inspected them in January last.

All three temples are built in the same style and appear to belong approximately to the same period. The style is that of Northern India, which Fergusson calls the Indo-Aryan, the period in all probability, is about the 10th century A.D. Mr. Krishna Sastri, the

Assistant Superintendent for Epigraphy. informs me that Mahendragiri has always occupied an important place among the sacred mountains of India from very early times, and he states that the epics $K\bar{a}m\bar{a}yana$ and the $Mah\bar{a}bh\bar{a}rata$ * all the $pur\bar{a}nas$ and the Kavya-literature make reference to it. The Vishnu Purana† mentions it among the kulaparvatas, i.e., the chief mountains of Bharata Varsha (India). The Sansarit poet Kalidasa mentions it in the course of his narrative of the victorious conquests of the Solar king Raghu‡.

Within historic times we find the mountain referred to in an inscription, at Nasik, of the Andhra king Vāsishthiputra Pulumāyi (II) (A.D. 135-163§), where he is stated to have been the lord of this and other mountains. Later, during the time of Gupta rule, the mountain and the country around it were included in that empire as we learn from the Mandasor inscription of Yasōdharman (about 589 A.D.||). The Chinese pilgrim Hiouen Tsang states that on the summit of a high mountain in the north of Kieling-kia (Kalinga) there was a stūpa of about 100 feet in height. It has been suggested that the Mahendragiri might be the spot referred to by him¶. General Cunningham thinks that, according to the pilgrim's account in the early years of the 7th century A.D., Ganjām lay in the dominions of Harshavardhana of Kanouj**. During the 10th, 11th and 12th centurier Mahendragiri Lecomes celebrated as the seat of the God Gōkarnēsvara, the tutelary deity of the Ganga kings of Kalinga++. Inscriptions found on or near the temples on the hill are not many. None of them, so far noticed, in the Epigraphical reports makes any reference to the early connections of the kings of Kalinga to the shrine of Gōkarnēsvara, its origin or growth. From two of the inscriptions, we learn that "a general of Rajēndra Chōla named in Tamil Rajēndrasōla-pallavaraiyan Rājarājamārāyan overcame the Kulūta king named Vimalāditya and set up a pillar of victory.‡‡ Who these Kulutas were whose lord was Vimalāditya, has yet to be determined. But the fact that the Chōla dominions in the 11th century extended so far north as Mahendragiri is noteworthy. From other historical introductions to his inscriptions we know that Rajēndra-Chōla's conquests extended even into the Gangetic valley.

During the 12th and 13th centuries, Mahendragiri with Ganjām shared common rule with the Andhra country. Gonka II, a chief of the Velanadu line who was in power about A.D. 1133 claims to have been the lord of the entire Andhra country extending from Kalahasti (Chittoor district) in the south to the Mahendragiri in the north§§.

Of these temples, the little shrine on the summit of the mountain known as Bhima's temple is in all probability, the earliest of the three. It is a small building standing only about 22 feet in height and about 10 feet square on plan but the size of the huge blocks of stone used in its construction is very remarkable. It contains a small shrine chamber and a particularly small entrance which faces the east. It appears to have been erected as a Siva temple but the building was never completed. The structure is crowned with a huge umbrella stone carved out of a single block of stone resting on a second rounded stone forming the circular shaft or necking for the superimposed umbrella ornament. The latter is provided with two stone rings, one on each side, to serve as socket holders for prayer flags or additional votive umbrellas. The building has obviously been struck by lightning, perhaps at the time when it was being built which would account for it being left in its. present unfinished state. From the simplicity of its style and its position on the summit of the mountain it was in all probability the first temple set up here. It contains no inscriptions, sculptures or images but on purely architectural grounds, so far as it is possible to judge from such an unfinished building, it would appear to belong to about the 9th century A.D. Although of no real architectural value, this little shrine is interesting as it shows us how such temples were constructed in early this little shrine is interesting as it shows us how such temples were constructed in early the need into home shlowly all the property and the property should be a shared into home shlowly all the need to be a shared and the property and the shared into home shlowly all the shared into home shared into home shlowly all the shared into home. in its construction were first quarried and then roughly shaped into huge oblong blocks, dressed only on three sides, the fourth side forming the outer face of the block was left in the rough and not dressed until all the stones had been set in position, and this was done without the use of cement or mortar between the joints of the masonry. The stones were kept in position by their own weight and the accuracy of their dressing and fitting. The nature of construction was much the same as that employed by a child when playing with a box of toy bricks. When all the stones were got into position, the builders started to carve the exterior surface of the structure into the form required, just as though the entire building had been a monolith or natural rock. This peculiar treatment of the building seems to indicate that its builders knew far more about the art of hewing temples out of the living rock than they did about the principles of ordinary stone construction. The big blocks of stone were no doubt got into position by being dragged and pulled up

^{*} See Ep. Ind., Vol. III, page 20, foot-note 5.
† Wilson's Translation, pages 176 and 177.
† Ind. Ant., Vol. VIII, page 6.
§ Arch. Surv. of W. India, Vol. IV, pages 107 to 109.

|| Fleet's Gupta Inscriptions, page 7.

|| Beals Buddhist records of the Western World, Vol. II, page 209, and note 67 thereon.

** Sewell's List of Antiquities, Vol. I, page 2; Fleet's Gupta Inscriptions, page 231.

†† See (a) Ep. Ind., Vol. III, pages 20, 133, 183 and 221; (b) Ep. Ind., Vol. IV, pages 185, 186 and 199; (c) Ind.

Ant., Vol. XII, pages 12, 123 and 273.

†† See Archæological Survey of India for 1911-12, page 171.

§§ Fp. Ind., Vol. IV, page 36 F., and Annual Report on Epigraphy for 1912, page 85, paragraph 65.

an inclined plane or ramp composed of earth and stones and in all probability, wooden rollers were used under the stone blocks to facilitate the work. Even with modern appliances, the handling of such huge blocks of stone for building purposes would prove no easy task. The fact that all carving and ornamentation to the structure was done after the blocks had been set in position, clearly shows that the primitive method of hoisting the blocks into position suggested above, was undoubtedly the means employed. Had the blocks been carved before they were set in position, there would have been the risk of the carved portions getting damaged in the process of building. The only portions of the building which were completed are the plinth mouldings and the umbrella ornament as may be seen in Plate X Fig. (a).

At a short distance from Bhima's temple, on the eastern slope of the hill, is the It is built in the same style as the last mentioned shrine, only Yudhisthira temple that the Yudhisthira temple is much larger and far more ornamental. It has the same conventionalised umbrella ornament and similar mouldings around its basement as those found in Bhima's temple described above. The umbrella ornament was originally surmounted by a stone finial or kalasa. This ornament is now lying on the ground on the south side of the temple and appears in the photograph given in Plate XI (a). It seems that it was the custom when fixing the kalasa to the summit of a temple in early times, to place a few precious stones or gold coins as a votive offering to the deity enshrined below, in the socket hole, before fixing the kalasa securely in position. The Zamindar of Mandasa informed me that this particular kalasa was thrown down by treasure-seekers some years ago. Perhaps the custom of placing votive offerings under the kalasa of a Hindu temple was copied from the Buddhist custom of placing valuable offerings in the tee of their stupas, above which they always placed one or more honour-conferring umbrellas, the Indian emblem of sovereignty and which in those days, also represented the highest honour possible that could be conferred on God or man. In form, this kalasa or finial belonging to the Yudhisthira temple is similar to those usually found crowning the mediaeval Buddhist temples and votive stupas found at Bodh Gaya and in Nepal. simple mouldings of the plinth too, are identical with some of those found in the earlier buildings of the Buddhists. On each face of the curvilineal tower over the shrine chamber is a carved representation of a large horseshoe-shaped window similar in form to those found in Buddhist buildings and which are known as chaitya windows. representations of windows are purely ornamental as they do not admit light or air into the interior of the building. Like the Bhima temple described above, the external ornamentation of the Yudhisthira temple was executed after the structure was built. This is particularly obvious on the northern side of the temple, here, the fluted ornament around the umbrella stone has been left unfinished. Part of the ramp too, still exists on this side and several blocks of cut-stone are lying on the slopes of the hill, midway between the place where they were quarried and the artificial ramp of earth and stones leading up to the north side of the temple. So in this case, there can be no shadow of doubt as to how these colossal blocks of stone were placed in position in the building and the size of some of the stones is most remarkable. For instance, the ornamental umbrella stone measures 9 feet 3 inches in diameter and is 2 feet 6 inches in thickness. The stone below it, forming the shaft or necking of the umbrella is 7 feet in diameter and 1 foot in thickness. The next stone below the last forms the top covering slab for the tower and like those above it is cut out of a single stone measuring 11 feet 4 inches square and is 2 feet in thickness. A reference to the plan and section given in Plates XII and XIII, gives one a far better idea of the construction of the building than a written description conveys. Like all early temples, there is no porch or mandapa in front of the entrance, the entire building consists of only a tomb-like cella 9 feet square surrounded by massive walls 4 feet in thickness. Since the floor of the shrine is below the level of the ground outside, the small entrance doorway is provided with three steps leading down to the object of worship which is a small stone linga of the usual kind. The entrance faces due west. Above the doorway, securely fixed in the stone lintel, are two forged iron girders about 3 inches in thickness and placed horizontally across the entrance in order to give additional support to the stone lintel above. The position of these iron supports is shown in the Section (Plate XIII) and are represented there by two little white squares imbeded in the under surface of the lintel. The position of the innermost girder, clearly shows that it was inserted at the time when sind structure was built and is not a later addition. tion. I remember finding similar iron girders only much larger than these, at the Sūrya temple at Konārak near Puri, generally known as the Black Pagoda. The walls of the cella rise to a height of twelve feet four inches when the curvilineal tower begins. It will be noticed that the dome-shaped tower is not a true dome, but merely composed of a number of courses of masonry projecting one above the other after the manner of corbels. In this way, the span of the tower is reduced as the height increases, until the top of the interior of the tower is reached when the corbels nearly meet. The opening here, is closed by a single huge roof slab (see Plate XIII). Around the upper portion of the walls of the cella are some faintly engraved inscriptions that have not yet been designed. deciphered. The characters are so faintly engraved that it is not possible to take rubbings or estampages from them. But they are sufficiently clear and legible to be read by any one who understands the language in which they are written. I tried a flash-light photograph but it proved a failure and a proper wooden platform would have to be set up inside the temple before the inscriptions could be photographed as they are situated at about ten feet above the floor level and are very difficult to get at and owing to the very small doorway the interior is particularly dark and gloomy. This peculiar method of cobelling the courses of masonry so as to produce a dome-like appearance within the building goes back to very early times. The dome-shaped roofs of the interiors of the bee-hiveshaped tombs of Mycenæ were treated in the same way, only the sharp angles of the corbels were cut off so as to produce a curved appearance to the surface of the stone walls. On the exterior surface of the stone lintel over the small entrance into the temple, is engraved in Sanskrit-Telugu characters, an inscription recording the conquest of Kālinga by the great Tanjore king Rājēndra Chōla I in the 11th century A.D. At the termination of the inscription is engraved a sitting tiger and three fish before it, the royal emblems of Chola Sovereignty. This is the jayastambha or pillar of victory recorded in the inscription cited above. The name pillar of victory is misleading as the so-called pillar is really the stone lintel over the temple doorway.

In front of the temple is a small courtyard or enclosure but like the temple itself, it was left unfinished. The size of some of the blocks of stone forming the walls of this enclosure are truly marvellous and their weight must be colossal. On the north side of the temple is a small well but this does not hold water all the year round and it is therefore of very little use to pilgrims and others who visit this interesting old monument. Surrounding the temple on the south and west sides, are a number of primitive little lings shrines built of rubble masonry. They cannot be of any great antiquity and were no doubt set up by pious pilgrims as memorials of their visit to the Yudhisthira temple. From the summit of Mahendragiri one gets a number of delightful views of the surrounding country and the sea is clearly visible for many miles along the east coast. The view given in Figure (b) of Plate XI, is only one of many picturesque views obtainable from the top of the mountain.

Fergusson in his "History of Indian and Eastern Architecture," does not explain the origin and development of the North Indian or Indo-Aryan temple as exemplified in the Yudhisthira temple. Those readers of this report who desire to know the origin of this type of Hindu temple, will find the subject explained and illustrated in my monograph on "The Influence of the Umbrella on Indian Architecture" published by Messrs. W. Griggs & Sons, London, as No. 122 of the Journal of Indian Art.

At a short distance further down the eastern slope of the mountain, picturesquely situated in thick forest, is the Kunti temple illustrated in Plate XIV. It is built of stone and in the same style as the Yudhisthira temple but it is obviously of a much later period. We know that the Yudhisthira temple was standing in the 11th century by the information recorded in the Chōla inscription over its doorway and the simplicity of the style of the building shows that it was built in all probability, at least a century before that date. The style of the Kunti temple on the other hand, is more elaborate and complicated. The latter is provided with a small porch in front of the entrance which faces the west. On each external face of the body of the building we have a large ornamental niche for the display of sculptured images. Above these niches and also over the porch, half way up the tower, is a projecting stone block on each face of the temple. On these blocks carved stone images were originally fixed. The plan of the temple is no longer a simple square cella as we find in the earlier example, but here, the interior walls of the cella are provided with large shallow niches five inches deep while the external angles of the shrine chamber are doubly recessed giving the building a star-like (or perhaps lotus-like) appearance on plan as may be seen in Plate XV.

The carved representations of Buddhist windows have disappeared and the simple plinth mouldings of the Yudhisthira temple are replaced in the Kunti temple by deeply cut boldly projecting mouldings connected together at intervals by vertical bands (see Figure b, Plate XIV). The difficulty of transporting huge blocks of stone for building purposes has been overcome here, by using small stones of convenient size. Even the umbrella ornament is no longer a single monolith but is composed of a number of small stones. Over the entrance of the porch is a carved representation of the Navagraha or Nine Planets, and over the entrance into the cella, in the centre of the lintel, is a carved seated figure with two arms, the hands of which hold lotus buds. This figure appeared to me to be intended for a female figure and if so, it may be meant to represent Lakshmi. As a rule, Lakshmi is usually depicted by two elephants worshipping her by pouring water over her from pots which they hold in their trunks. If the figure is a male figure, then in all probability, it is intended for Sūrya the Sun God. Lying in the courtyard of the Yudhisthira temple I found a broken portion of a red sandstone image representing the legs and feet of Sūrya with the seven horses below the feet. The size of this broken image indicated that in all probability, it originally stood in one of the side niches adorning the exterior walls of the Kunti temple. A similar red sandstone image of a female figure unfortunately, too decayed for identification, still exists in the niche on the north side of the Kunti temple. The niches on the south and east sides have been filled with modern granite images of Ganesa and Subramania respectively, and a stone linga and yoni stand were placed in the cella two years ago by the Zamindar of Mandasa.

Another indication that the Kunti temple was originally a Vaishnava shrine, is the red sandstone chakram shown in Figure b, Plate X. This emblem of Vishnu. I found lying on a heap of stones by the side of the Kunti temple. It is possible that this ornament originally crowned the umbrella stone or it may have been fixed to the projecting block of stone above the porch of the Kunti temple.

Standing in front of the Kunti temple and facing the east is a small ruined shrine containing inscriptions on its doorjambs. The latter and the plinth mouldings of the original shrine alone remain. The rest of the structure represents modern repairs executed by order of the Zamindar of Mandasa. These inscriptions were copied and registered in the Epigraphical Report for 1896, and their purport is mentioned in Mr. Krishna Sastri's Note on the history of these temples from the inscriptions quoted above. Inside this little shrine is one large and one small image of Vishnu. It is obvious that the large image at least, does not belong to this little shrine and that it has been placed here at some later date. The smaller image of Vishnu is carved in similar red sandstone to those mentioned above, and its size seems to indicate that it has been removed from one of the exterior niches belonging to the Kunti temple. It is possible that this little temple may represent the remains of the old Gokarnesvara temple mentioned in the inscriptions. The Savaras, the local jungle tribe who inhabit the forests covering the slopes of these mountains in this part of the Ganjām district, call the Kunti temple by that name, but the Zamindar of Mandasa calls the Kunti temple the Gōkarnēsvara temple. The Kunti temple contains no inscriptions to guide one as to whether it was originally dedicated to Siva, Vishnu, or Sūrya. Kunti also pronounced Kointa by the Savaras, cannot mean anything else than the Puranic name of the mother of the five Pandavas. No doubt the name Kunti, as the correct name for this particular temple, has been known to the Savaras from the time when it was first built, which in all probability, would be about the 12th century A.D. The Savaras certainly occupied these forests long before the temple in question was built and it is unlikely that they have forgotten its correct name or at least the name they originally gave it, when that they have long or that it. So far as I am aware, there is no evidence whatever, that the temple in question was originally dedicated to Siva or that it was ever known as the Gökarnesvara temple. The linga, the images of Ganesa and Subramania, together with the small stone bull set up in front of the entrance to the Kunti temple, all represent modern additions which have no connection whatever with the original temple. For the present, and until some evidence to the contrary is forthcoming, I am inclined to think that the Kunti temple was originally a Vaishnava shrine dedicated to Vishnu or Sūrya and that the small ruined shrine facing it with the inscribed doorjambs, was originally a Siva temple known as the Gökarnesvara temple.

CONSERVATION NOTES

Gingee Fort, South Arcot district.—The history of Gingee Fort and a brief description of the chief buildings it contains is given in the South Arcot District Gazetteer, pages 347 to 362. It stands on three high hills, connected together by massive fortifications arranged in the form of a triangle. The triangular space enclosed is about three miles round and forms the lower fort, and the three hills are the citadels. The lower fort was originally entered by two gates, one on the north, called the Arcot (or Vellore) gate, and another on the east, known as the Pondicherry gate.

Up each of the three citadels leads, from the lower fort, a steep flight of steps of hewn granite built with much skill on and among the great boulders with which the hill sides are strewn. The citadel on the north is called Krishnagiri, that on the south, Chandrāyan Drug, and that on the west, the highest and most inaccessible of the three, is named Rājagiri.

Rājagiri was the chief citadel of the fortress and the portion of the triangular lower fort which lies below it is occupied by an inner fort surrounded by a high wall protected by bastions fitted for guns and a deep moat, and the only path to Rājagiri leads through this and up the ridge.

The most interesting buildings are situated in the two citadels on Rājagiri and Krishnagiri, respectively, and also in the centre of the inner portion of the lower fort. The ruined citadel on Chandrāyan Drug contains no buildings of any architectural importance and I do not consider any steps are necessary to conserve this portion of the fort. It is impossible to preserve the entire fort, neither is such a course necessary. It will be sufficient if we select, for conservation, those portions of the fort which contain the best buildings and which are of most historical value. These may be briefly described as follows:—

1. Rājagiri.—On top of this hill is a fairly level space covered with rough hill-grass, on which are situated a temple to Ranganātha, a mandapa, two big granaries, a masonry flag-staff, a building of unusual design which is supposed to have been an Audience Hall, and another with a roofless tower and a chamber under its floor which is called "the Treasury". A little lower down the hill in a small mandapa on its southern side, is a large cannon. These seven buildings, together with the old mandapa containing the cannon, should be preserved from further decay. This can best be done by plastering the

exposed tops of ruined walls with rough plaster, and patch repairs to the roofs where necessary. All rank vegetation should be removed and proper drainage provided. The tops of the ruined parapet walls of the fortifications should be repaired where necessary to prevent accident to visitors. The large building generally known as the Audience Hall and recently repaired should be plastered and white washed inside from roof to floor. It should be provided with an iron gate-way which should be kept locked and the key should be in the custody of the Public Works Department Overseer stationed at Gingee.

- 2. Krishnagiri.—On the top of this hill are two stone-built granaries, two mandapas, a deserted temple to Ranganātha, and a brick and plaster building with a domed roof known as the Audience Chamber. All these buildings should be preserved from further decay in the manner stated in detail in my printed Inspection notes dated the 31st August 1915. The parapet walls of the fort at this point should also be repaired where necessary to prevent accident. The buildings require cleaning out and provision for proper drainage should be made where necessary. At present the main approach to the citadel runs up the middle of the hill. This is in a very bad state of repair owing to so many of the stone steps having got out of place. A better and more convenient approach could be made by repairing the long flight of steps leading up from the line of ramparts which connects Krishnagiri with Chandrāyan Drug. These steps lead straight up to the walls of the citadel where they abruptly stop. At this point, a new entrance should be made through the wall of the citadel and, henceforth, this should constitute the main approach for visitors entering the citadel from below. The steps are in fair order and most of the parapet wall on this side is in good condition. Where necessary, this wall should be repaired in order to prevent accident. All the existing portions of these ramparts from Krishnagiri to Chandrāyan Drug should be saved from further decay. All rank vegetation should be removed, the ground cleared of all rubbish, levelled, and sloped for drainage. The same remarks apply to the terrace below these ramparts along the margin of the most from hill to hill. Care should be taken to retain all existing portions of the brick and plaster loop-holed parapet wall which originally served as battlements to the ramparts. All the curious little brick and plaster sentry boxes along the ramparts on this side should be preserved from further decay.
- 3. The road from Tindivanam to Tiruvannāmalai has been led straight through the lower fort by two gaps made in the walls. These two gaps should be roughly repaired by stepping up the broken walls with granite blocks and dressing and sloping the earthen ramparts to prevent scouring in the rains and to improve their present unsightly appearance.
- 4. The historical Arcot (or Vellore) gate, the Pondicherry gate and the Royal Battery constructed by the French, have all been selected for conservation and their repair is in progress.
- 5. Sādat Ulla Khan's Gate.—This forms the inner gateway to the Pondicherry gate, and is sometimes called the "Jail." It contains an inscription in Persian commemorating Sādat Ulla's victory over the Hindus and his capture of the fort, and giving the date assHijra 1125, which began on January 17, 1713 A.D. Vegetation has been removed, the missing parapet wall around the flat roof over the cells is being repaired and a proper roadway fit for motor traffic will be made to Sādat Ulla's mosque.
- 6. Sādat Ulla's Mosque.—The Persian inscriptions over the gateway of this mosque and on the adjoining water tower, record that these were built by Sādat Ulla in 1717-18 A.D. The mosque is of no architectural value, but it is worth saving from further decay on account of its historical interest.
- 7. Venkataramana temple.—Architecturally, there is nothing remarkable about this structure, but it is of sufficient historical interest to justify prevention from decay and it is also a picturesque old ruin. The lofty gopuram or tower over the east gateway of the temple requires the removal of all signs of vegetation from the masonry. The top of the roof and numerous cornices should be replastered after the removal of all vegetation. Stone lintels should be provided to all the ruined window openings where the old teakwood lintels are missing.

These repairs are now in progress and will be completed shortly.

- 8. Pattābhi Rama temple.—The main shrines are too decayed to justify any repairs, other than the removal of rank vegetation. The tower over the eastern gateway should be provided with a new roof and saved from further decay in the same manner as that proposed for the tower over the eastern gateway to the Venkataramana temple described above. The handsome twelve-pillared mandapa in front of the temple and the smaller four-pillared mandapas on each side of it should be saved from further decay by patch repairs where necessary and the provision of proper drainage around their basements. At least 20 feet of ground should be acquired all round the big twelve-pillared mandapa, and this area should be marked out with boundary stones firmly planted in the ground to prevent encroachment by the ryots.
- 9. Repairs to the large granary, the Venugopala temple, the west gateway of the Inner Fort, the Kalyana Mahal and Barrack Square, and the Gymnasium are now being undertaken by the Public Works Department.

- 10. Pristner's well.—On top of the ridge above the Chakkrakulam tank is a prominent boulder about 20 feet high surrounded at the top by a circular brick parapet wall. It has a natural hollow passing through it like a well, and the bottom having been blocked up with masonry and the sides smoothed with plaster a natural dry well was formed into which prisoners are said to have been thrown and left to die of starvation. The top of the boulder can only be reached by means of a ladder. The brick parapet should be inspected and repaired if necessary.
- 11. Hanumān image.—Between the Chettikulam and Chakkrakulam tanks is a large image of Hanumān carved in bas-relief on a natural slab of rock. Originally, a four-pillared mandapa was erected over it. This has now fallen and the villagers propose to rebuild this mandapa at their own expense as they still worship the image in question. The image is of no archæological or artistic value and I see no objection to their proposal to rebuild the mandapa. There is plenty of stone available at the site for this purpose. The work should be executed under the supervision of the Local Public Works Department Overseer.
- 12. General remarks.—It is impossible to refer in detail to all the numerous bastions, temples, mandapas and other ruined buildings which are scattered all over this great area. Many of the temples have been seriously damaged by treasure seekers and parts of others have been carried away to decorate neighbouring shrines. In my opinion, it will be quite sufficient if we conserve those portions of the fort and buildings enumerated above and described in detail in my inspection notes already submitted to Government.
- 13. Arcot Fort, North Arcot district.—At the suggestion of Mr. F. J. Richards, I.C.S., Collector of the North Arcot district, I inspected the old ruined fort at Arcot with a view to submitting proposals for its future preservation.

It is recorded in the Manual of the North Arcot district, Volume II, pages 306 to 307, that the old city of Arcot was surrounded by a high rampart nearly 5 miles in circumference, 24 feet broad at the base and 12 feet at the top, and faced with a thick masonry wall. This was called the Shāhārpāna or "defender of the city," and had five gates, the chief of which was the Delhi Gate, which led out upon the bed of the Pālār. The northern wall followed the course of that river, and in parts had a moat, with strong bastions at intervals embrasured for guns. The whole is now in complete ruin, having evidently at some time been blown up, for enormous masses of masonry lie in confusion about its foundations. In 1811 a flood in the river undermined some portions of the northern wall and still further completed its ruin; but the Delhi Gate still stands, thanks to the care bestowed upon it by Government. Within the city walls, and about half a mile from the river, are the ruins of the citadel, or inner fort, so gallantly defended by Lord Clive in 1751. It was a rectangular fortness of considerable size, surrounded by a shallow moat, probably fed from the Pālār. Like the Shāhārpāna, its walls have been utterly destroyed with the exception of a large but ruined bastion which originally defended the north-eastern angle of the citadel. Its enclosure, as well as the moat, are now under cultivation and the only buildings which survive within are a small mosque and two ornamental tanks, together with an old iron cannon, all of which are situated close together on the south-western side of the fort. Within a few yards of these structures, on the northern side of them, is a large mound of earth which appears to indicate the site of another old bastion. In order to preserve what remains of these interesting historical ruins, the following buildings have been selected by Government for conservation:—

The Delhi Gate, the north-eastern portion of the Shāhārpāna, the north-eastern bastion of the citadel, the mosque in the citadel together with the two ornamental tanks and the old iron cannon situated in front of the small mosque which is said to have been used by the late Nawab of Arcot as a place of worship.

- 14. Sampalli temple, Chittoor district.—The village of Sompalli is situated at a distance of four miles to the east of Mulakalacheruvu railway station in the Madanapalle taluk of the Chittoor district. It contains a handsome little Vishnu temple known as the Chennakēsava temple. Considerable repairs have been carried out to this temple by the Public Works Department and the building is now in good condition.
- 15. The Mōtupalle temple, Guntūr district.—Situated in the small village of Mōtupalle in the Bāpatla taluk of the Guntūr district is a small Chola temple bearing ancient inscriptions of considerable historical interest. These were copied by the Assistant Archæological Superintendent for Epigraphy and published in 1909-10, and registered as 600 to 603 of Appendix B in the report on Epigraphy for that year. Paragraphs 45 and 61 of Part II of the same report give a detailed account of the purport of the inscriptions in question which is as follows:—

The Mōtupalle record is interesting as being a charter granted by Ganapatidēva Mahārājā to merchants trading on sea, whose vessels used to call at or start from the seaport of Mōtupalle, otherwise called Dēsivuyyakkondapattana. These vessels are stated to have been trading with islands and coast towns in distant countries. The necessity for the charter was that kings of old used to confiscate by force all the cargo of any vessel driven by unfavourable weather on to shore. "Seeing that protection (of my subjects) is

far more important (to me) than my life," says Ganapati, "we have remitted out of compassion all (taxes) except kupasulka on these enterprising (merchants) trading on the sea in order to secure fame and to maintain the principles of a righteous Government." The details of kupasulka tax, which somewhat resembles our custom-house duties, are rectrated in the Mōtupalle inscriptions. They comprise fees on sandal wood, country (?) camphor, china-camphor, pearls, rose-water, ivory, civet, camphor-oil, copper, zinc, resin, lead, silk-thread, coral, perfumes, pepper and areca-nuts. This long list of cargo shipped by the merchant vessels at Mōtupalle corroborates the glowing account given by the famous traveller Marco Polo on the prosperous trade carried on at the sea-port town of Mutfili (Mōtupalle), when he visited it during the reign of the Kākatīya Queen Rudramadēvi, about the end of the thirteenth century.

- In G.O. No. 1551, Public, dated the 29th October 1915 orders were passed by Government to safeguard this interesting monument from further decay as it had been neglected by those in charge of it. Henceforth, the temple will be maintained in good repair by the Public Works Department if the trustees are not in a position to look after it properly themselves.
- 16. Conjeeveram temples, Chingleput district.—Owing to the inferior nature of the sandstone used in the construction of the Conjeeveram temples, their preservation has proved a difficult matter for the Public Works Department. Even when first quarried, the sandstone appears to have been full of holes, cracks and fissures which were filled up with brick and mortar where necessary, at the time of construction (second half of the seventh century). In order to hide these defects the temples were thickly plastered and white-washed and the ornamentation was mainly stucco work. Considering the age of the temples and their faulty construction, it is not surprising to find that much of the plaster work has decayed and fallen exposing the brick and stone work below. In order to preserve the buildings thoroughly, it would be necessary to replaster them from top to bottom and reproduce all the old stucco ornament at the same time. Such a course would of course give these ancient buildings a brand new appearance and utterly ruin them from an artistic point of view. In the circumstances, the repairs will have to be restricted to grouting and pointing open joints, cracks and holes with specially prepared mortar or cement, coloured to match the old work. There is no necessity to restore or attempt to reproduce any of the stucco figures or decorative features in the buildings. The cement used should match the colour of the masonry and should be confined strictly to the joints, holes, cracks, etc., and in no case should it appear on the surface of the adjacent masonry. In order to guard against this in future, all new pointing, filling up of cracks, holes, etc., should be recessed one-eighth of an inch.

 17. Shermadevi temple, Tinnevelly district.—On account of the historical value of the

17. Shermadevi temple, Tinnevelly district.—On account of the historical value of the inscriptions and the handsome stone carvings on the outer walls of its shrine chamber, the Bakthavatsala temple at Shermadevi was included in the Standard List of Ancient Monuments for the Madras Presidency, in G.O. No. 276, Public, dated the 29th February

1912.

A sum of Rs. 340 was spent by Government during 1914, in relaying the terrace roof over the main shrine and part of the roof over the verandah of the inner enclosure, constructing a drainage outlet pipe to drain the courtyard round the sanctum and pointing the pavement of the courtyard and relaying disturbed flagstones.

I inspected the temple in question on the 17th September 1915 and found the repairs mentioned above had been neatly carried out.

- 18. Kodandarama temple at Vontimitta, Cuddapah district.—The iron girders and supports for the cracked stone beams and roof slabs of the lofty gateway of the temple on the east side have now been fixed and this gateway is no longer in danger of falling.
- 19. Siddhavattam Fort.—When I inspected this picturesque old monument in September last, I discovered a clear and legible inscription engraved on the outer wall of the east gateway which I brought to the notice of the Assistant Archæological Superintendent for Epigraphy for copying and decipherment. He informs me that the inscription in question is a record of the 17th century, dated 1605-06 A.D., and relates in Telugu verse that the chief Anantha Rājā of the Matla family, who was a subordinate of the Karnata King Vira-Venkatrāya (i.e. Venkata I) constructed a tank at Siddhavattam and either built or improved the fort at that place. Anantha Rāja's conquests and his literary composition called Kākusthavijayamu, are also referred to. His father Yellamarāju is stated to have subdued a certain Kondrāju Tirupattirāju and captured from him the town of Siddhavattam.

The fort is included in the Standard List as item No. 167, and it has been repaired at Government expense by the Public Works Department in the past. The only portions of the fort to be kept in a thorough state of good repair are—the gateways on the east and west sides respectively, the mosque known as the Purkota Masjid and the tomb along side of it known as Bismilla Shavali Gummaz.

20. The removal of sand from the groups of buried temples at Joti on the north bank of the river Pennar close to Siddhavattam, reveals that these temples are of no architectural value and that they are not worth repairing at Government expense. The

following sculptures unearthed however, should be packed in wooden cases and despatched to the Government Museum, Madras:—The two stone images of Sūrya, the spacened to the Government Museum, Madias.—The two stone images of Surya, the large image of a worshipper now in the little shrine half-buried in sand, and the female Nāga or Nāgi image. There is also an uncommon stone linga which has carved on its upper portion four faces of Siva. These four sculptures and the linga in question, I pointed out to the Public Works Department Overseer on the spot and asked him to arrange to have them carefully packed and despecthed to Madras.

- 21. Near the main gateway of the enclosure walls around the half-buried shrines at Joti, I found a large stone slab set up vertically in the ground and bearing ancient inscriptions. This I reported to the Assistant Archæological Superintendent for Epigraphy for decipherment. That officer has since informed that the inscription in question is dated Saka 1169 Piavanga (1247-48 A.D.) and belongs to the reign of a certain Rayidēva Mahārāja, surnamed Rakkasa Gangarasa. Chenti Rāma Nāyaka, a servant of this king and a devotee of Jōtinātha (i.e. lord of Joti) built the surrounding enclosure walls and the gopuram or gateway for that temple. He also built a temple for Irugula-sāmi at the village of Takaprōlu (now the modern Takkōlam) close to Joti, dug two tanks at Chettūru, built a temple there and granted a village to Brahmans. Mr. Krishna Sastri informs me has not met with the name of this king before so the record is of interest and value. In order to safeguard this old record from further decay I would suggest that it be removed to the Taluk office at Siddhavattam for safe custody. Should there be any local objection to its removal from the temple enclosure, it should be set up inside the temple gateway where it would escape exposure to sun and rain.
- 22. Pushpagiri.—The repairs to the attendant temples and the roof over the gateway of the Vaidyanatha temple at Pushpagiri have been completed and they are now in good order. However, it will be necessary to excavate the ground down to the plinth line of the buildings and slope and dress the ground all round to ensure proper drainage. All loose stone and rubbish in the temple courtyard should be removed and the ground levelled and made tidy after proper drainage has been provided. The temple authorities desire to remove the ruined shrine near the entrance gateway and use the stone for repairing the compound walls in order to prevent cattle trespass. There is no objection to this as the ruined shrine in question is of no archæological interest. The repairs to the compound walls should be carried out by the Public Works Department as the temple authorities have no funds for the purpose.

23. Kesava temple.—This temple is situated on the north bank of the river and faces the village of Pushpagiri. No repairs are required at Government expense.

24. Srīsailam, Kurnool district.—At the suggestion of Mr. H. A. B. Vernon, I.C.S. late Collector of the Kurnool district, an estimate amounting to Rs. 6,700 was framed by the Public Works Department for repairing the ruined attendant shrines, mandapas, verandahs and gateways belonging to the famous Mallikārjuna (Siva) temple at Srīsailam, a place of great sanctity to Saiva Hindus, situated in the forests covering the Nallamalai Hills on the southern bank of the Krishna river in the Nandikotkur taluk of the Kurnool district. The temple is under the management of the Brahman pontiff Samkarāchāryasvāmın of the Pushpagiri-Matha in the Cuddapah district and this gentleman ought to feel thoroughly ashamed of himself for the disgraceful manner in which he has allowed this interesting group of buildings to fall into a serious state of disrepair. If the funds collected annually at the Sivarātri festival had been utilised properly and honestly in maintaining these buildings in good order, the temple would never have got into such a bad state of repair. The cause of its ruin is entirely due to gross neglect on the part of those in charge of its management. It is of course, quite unnecessary to carry out any repairs at Government expense and it is to be hoped that the Brahman community itself will see that in future, the funds collected from the pilgrims are not misappropriated by those in charge of the management of this famous religious institution. At some future date, when time permits, I hope to include in my Annual Report, an illustrated article on this wonderful old temple. To attempt to describe it without the aid of illustrations would be a waste of time and prove very uninteresting reading, so I must let the matter stand over for the present. Mr. Krishna Sastri has published a very interesting account of the epigraphs secured from this temple last year, in his Annual Report on Epigraphy for 1915, pages 91 to 93. During my inspection, I had a site plan of the buildings prepared and photographs taken of everything there of any historic or artistic interest. A list of these photographs is given in Appendix A.

25. Ahōbalam.— In February last, I inspected the Vaishnavite temples at Upper and Lower Ahōbalam respectively. The Ahōbalam temples are to the followers of Vishnu what the Srisailam temple is to the Saiva Hindus of this district. These temples are situated about 32 miles to the south of Nandyal railway station. The lower or Diguva (sometimes called Chinna) Ahōbalam is at the foot of a small range of wooded hills. Upper, or Pedda-Ahōbalam is situated in a rocky bed of a small stream with a number of smaller shrines built all round on the neighbouring peaks. Architecturally these temples are not particularly remarkable but they contain a few historical inscriptions. These have been published on pages 94 to 96 of the Annual Report for Epigraphy for 1915. They belong

to the Vijayanagar period following that of the great Krishnadeva Rāya and deal with provision made for offerings to the God, construction of tanks and feeding houses, the planting of groves and gardens, etc. On his way to his victorious compaign against Kalinga, Krishna Rāya visited Ahōbalam and presented to the God Narasimha a gold necklace with a pendant set with an emerald and diamonds, wristlets set with rubies, a gold plate and one thousand pieces of gold. A curious story in connection with Ahōbalam is the supposed marriage of the God Narasimha with a Chenchu woman of the Nallamalai forest. The event is seriously believed by the pious devotees of the temple and forms the theme of the Sanskrit drama Vāsantikāpartinaya. Images of Lākshmi, the consort of Narasimha and his Chenchu wife Chenchu-Lakshmi or Chenchu-Tāyar not only figure in the bas-relief sculptures adorning the western side of the inner gateway and on some of the pillars of the unfinished Ranga Mandapa of the temple but also metal idols of them are worshipped in the central shrine. At Upper Ahōbalam, the God is represented by a figure of ten-armed Narasimha standing in a natural cavern in the rock. Near it, in the verandah is the Chenchu bride of the God, on whose account the Chenchus became the votaries of Vishnu and enjoy certain fees at the festival; near to this is a deserted room of Vishnu's lawful wife, Lakshmi, who, being offended at her husband's faithlessness, is said to have gone up the hill and taken up her abode on the top of the Momukonda peak. Here, upon one of the precipitous sides of a deep ravine, is an iron pillar which barren women solicitous for children circumambulate and adore. The shrine is alleged to have been first established by Pratāpa Rudra, the supposed founder of the town of Rudravaram in the fourteenth century. The earliest inscription discovered by Mr. Krishna Sastri at the two Ahōbalams, belongs to the time of the Reddi king Kātama-Reddi Vēmā-Reddi of the early part of the 15th century A.D. and records the gift o

26. Kurnool Town.—The repairs to the handsome tomb of Abdul-Wahab-Khan have been completed, this monument is now in good repair. It was in the beginning of the 17th century, when Abdul-Wahab was deputed by the King of Bijapur, with a powerful army, to take the fort of Kurnool. He arrived before Kurnool and besieged the town, which was then ruled by the last of the Hindu rulers, Gopala Rājā, a grandson of Rāma Rājā of Tālkōta. Gōpala Rājā stoutly defended the town, which was strongly fortified. He was assisted, it is said, by a force sent by Venkatapati of Penukonda. Gōpala Rājā, however was eventually obliged to yield, and he is said to have fled from the town through the northern gateway of the fort still known as Gōpal Darwaza. The remains of Gopala Rājā's palace still exist in the town and at the suggestion of Mr. H. G. Stokes, I.C.S., the present Collector of Kurnool, I inspected these remains with him in February last and I agree with him that they are worth saving from further decay and should henceforth be properly conserved. The palace is built in the Indo-Saracenic style of architecture and the ruined facade contains some excellent stucco ornament and uncommon window screens of great beauty. The appearance of the facade of the building has been spoilt by the later addition of a lofty wall with arched openings which was set up by the Muhammadans to enclose a small burial ground located between the ruined palace and the road in front of it. The town of Kurnool contains many very picturesque old buildings and portions of the ruined fort, but I do not think they are of sufficient historic or architectural value to justify any subvention by Government on their behalf. The tomb of Abdul-Wahab-Khan and the ruined palace of the last Hindu ruler, Gōpāla Raja, are the most interesting buildings in the town both architecturally and historically and these will henceforth be maintained in good repair as ancient monuments. Abdul-Wahab is said to have been an Abyssinian and a very bigetted Muhammadan. He governed Kurnool as a deputy for about sixteen years and gradually took possession of the neighbouring towns and taluks. He died in 1618 A.D. and was buried in a large and handsome tomb which he had built on the banks of the Handri and which has just been successfully repaired by the Public Works Department.

27. Malkapuram Inscription, Guntur District.—In the Annual Report of this Department for 1914-15, page 4, paragraph 16, a description is given of a very interesting and valuable inscribed marble pillar which I discovered at Ipuru, a village 13 miles to the north of Vinukonda in the Guntūr district. This year, we are indebted to Mr. J. Ramayya Pantulu Garu, Deputy Collector in the Guntur district, for the discovery of another inscription. relating to the same early period and to the same dynasty. Mr. Ramayya Pantulu Garu's report on his valuable discovery is embodied in a note printed in G.O. No. 934, Public, dated the 15th June 1915, and is as follows:— "In the village of Malkapuram in the Guntūr taluk, there is an old Saiva temple dedicated to Visvesvaraswami. The temple is now in a ruined condition and the idol is said to have been removed to Amaravatimany years ago.

In front of this temple is a huge slab of stone containing a Sanskrit inscription on three sides. The slab measures 14' 7" × 2' 10" × 2' 8" and is one of the largest inscribed stones found in Southern India. The inscription is of the time of Kakatiya King Ganapati Deva of Warangal, and shows that along with the temp'e there were established in the village (which was then called Visvesvarapuram) a Sanskrit College, a Student's hostel and also a Maternity Hospital—a rare thing for those times.

The inscription also contributes to the solution of a controversial point in connection with the history of the Kakatiya dynasty, viz., whether Queen Rudramma was the widow or the daughter of her predecessor Ganapati. The Italian traveller, Marco Polo, who landed at Motupalli during the reign of Rudramma is responsible for the statement that Rudramma was the widow of Ganapati. On the other hand, in the Sanskrit book Pratapa Rudrayam, which was dedicated to Rudramma's grandson and successor, Pratapa Rudra, Rudramma is said to be Ganapati's daughter. The Malkapuram inscription supports Pratapa Rudriyam and being the original record which came into existence during the lifetime of Ganapati and Rudramma, it is of the highest evidential value on the point. The inscription is thus of great historical importance and I beg to suggest that Government may be moved through the Superintendent of Archæology, to include the slab in the list of ancient monuments to be conserved in this district. The slab lies flat on one side, so that the inscription can be read only on two sides. It requires to be set up on a pedestal which can only be done by the employment of a large number of persons under skilled supervision."

Orders have been issued by Government for setting up the slab on a masonry pedestal so as to make all the inscriptions easily visible and it is now included in the Standard List of Ancient Monuments.

28. Madras City.—At the suggestion of Mr. H. A. Shore of the Public Works Department, the historical tomb of Messrs Elihu Yale and Joseph Hymners, situated in the compound of the Law College in Madras, was permanently included in the Standard List of Ancient Monuments, in G.O. No. 730, Public, dated the 10th May 1915. Elihu Yale and Joseph Hymners were both historical personage having both acted as Governors of old Fort St. George. Their careers are set forth in detail in Colonel Love's "Vestiges of Old Madras". It is the only tomb left from the old European Cemetery that once occupied the present site of the Law College.

29. Tanjore Palace.—The Palace is a peculiar structure with a bewildering series of large and rambling buildings. No definite plan appears to have been followed and a particular whim or requirement seems to have been the idea adopted. The result is a curious mass, in which beauty plays a secondary part. It is said to have been built about 1550 A.D., but many of the buildings appear to belong to a much later period and exhibit a considerable amount of European influence in their style and ornamentation and the result is anything but pleasing. Entrance is secured by way of a large quadrangle court-yard planted with trees, the enclosure walls being pierced by large gateways. After passing through a second quadrangle, a third is entered, on the south side of which is a lofty eight-storeyed building designed like a temple gopuram or pyramidal tower usually erected over temple gateways. This building was once the Armoury. It is an ill-designed and clumsy structure built on very poor foundations with the result that a considerable amount of settlement has taken place. In order to prevent any further settlement and thus save the tower from falling, the walls of the ground floor have been strengthened by the Public Works Department by introducing a number of additional brick arches, cross walls and buttresses and proper drainage to prevent water accumulating along the plinth line of the building has been provided.

On the east side of the inner quadrangle is the Telegu Durbar Hall of the Nayakkar Kings. This building is also called the Statue Hall on account of the fine marble statue of Sarabhoji the last Raja, but one, which it contains. On the walls are hung a number of badly painted portraits of some of the old Rajas and standing on a kitchen table placed against one of the side walls, I noticed a fine bronze bust of Lord Nelson, presented to the Raja by the Hon'ble Anne Seymour Damer, whose work it is. This curious building is of some historic interest but architecturally it is a failure as may be seen in Plate XVI. The European pillars and the balustrade above the cornice, the Muhammadan arches and the Hindu stucco ornament along the cornice and in the spandrels of the arches, gives the building a painfully vulgar appearance. The illustration given in plate XVI Fig. (a), shows the condition of the building when I first saw it. I was told that the unsightly matting provided for the upper portion of the arched openings between the front row of pillars and the dilapidated verandah also covered with grass matting, set up in front of the facade were necessary in order to protect the interior and the pictures contained within from the effect of the sun and rain. In order to do this and at the same time remove the matting and the unsightly shed in front, I requested the Public Works Department to fix glazed fanlights in the arches and provide the under side of the fanlights with hooks and chicks which could be raised or lowered as required. Figure (b) of the same plate, shows the appearance of the building now that these improvements have been carried out. The bronze

bust of Nelson will be set up on a masonry pedesual and the dilapidated railings in front of the hall will be repaired so as to give the front of the building a neat and tidy appear-

Architecturally, the large hall known as the Saugīta Mahāl is by far the most interesting of all the numerous buildings belonging to Tanjore Palace. It is said to be a miniature of the surviving court of Tirumala Nayak's Palace at Madura. It has been kept in good repair by the Public Works Department for some time past and this year sanction has been accorded to convert this building into office quarters for the Tanjore District Board. No doubt, some people will look upon this step as an act of vandalism. Personally, I look upon it as an act of common sense as it seems to me that it is better that a large building like this which has been in the past utterly useless and its maintenance costly to the Government, should be adapted to modern requirements and used for some useful purpose. The modern improvements now required have not seriously injured its original character or spoilt its architectural beauty and its historic value remains the same as before. Now that the building is in use as an office also insures its being maintained in a thorough state of good repair in the future.

30. Vellore Fort.—The old fort of Vellore is perhaps the most beautiful specimen of military architecture in Southern India and, fortunately, it is in a very good state of preservation. A brief description of its main features and history will be found on pages 417 and 418, Volume II of the North Arcet District Gazetteer. Within the fort is a large Siva temple no longer used for worship and maintained in good repair as an ancient monument by the Public Works Department. The most remarkable portion of this temple is the truly magnificent pillared hall known as the Kalyana Mandapa situated in the southwest corner of the first enclosure around the temple. Although very much smaller than many of the famous pillared halls found at Madura, Vijayanagar and elsewhere, it is in my humble opinion, the most beautiful building of its kind in Southern India. I obtained a number of photographs both of this temple and the picturesque fort during my inspection of these two interesting and beautiful monuments in March last and a list of these is included in Appendix A.

31. Hampi Ruins.—In 1912, I was of opinion that the extensive repairs proposed by me for the future preservation of the ancient remains of the Royal City of Vijayanagar, popularly known as Hampi Ruins, would take four years to complete and I requested the Government to appoint a special overseer for this work in order that the repairs might be carried out according to my conservation proposals set forth in Part II of the Annual Report of this Circle for 1912-13. This estimate of time has proved correct and all the monuments of paramount importance have since been successfully repaired and these buildings are now in good order. Further improvements will be carried out and some of the minor monuments still require attention and the proposed road to the famous Vittala temple has yet to be completed. Owing to the vast number of buildings to be conserved, the roads and pathways to be maintained, extensive annual repairs will always continue to be necessary. But the really important and expensive repairs may now be regarded as having been completed and I consider that the officers of the Public Works Department concerned, are to be congratulated on the excellent results achieved as some of the repairs were of a very difficult nature. The picturesque old tower over the eastern gateway or the Pattabi Rama temple which is a landmark for miles round, was a mere empty shell in immediate danger of falling when we first took it in hand. Although gateways of this type are common enough in Southern India, it seemed a pity to let this one collapse without attempting to save it. All the teakwood landings of the six storeys and the wooden lintels supporting the window openings on each side of the tower had vanished leaving only an empty shell of brickwork without any cross supports. The windows have been repaired with new brickwork and the holes in the barrel-vaulted roof closed with brick and plaster, and brick supports have been provided inside the tower to give additional support where necessary. As the main entrance to this temple is now on the north side facing the high road, this entrance on the east side has been closed by a dwarf wall as it is no longer required and goats and cattle used to foul the interior of this gateway. Plate XVII (A) shows the condition of this tower before it was repaired, Figure (b) of the same Plate shows the structure after repairs.

All the chief monuments at Vijayanagar are referred to in detail in Part II of my Annual Report for 1912-13 and there is no necessity to refer to them again here. sufficient and pleasant to be able to relate in this report that these interesting and valuable remains are now in a good state of preservation and visitors to Hampi will find better accommodation at the Travellers' Resthouse at Kamalapur and better roads and pathways to the monuments than ever existed prior to 1912. It is to be hoped that the amount of care and money bestowed on these national monuments by the Government will be appreciated by the educated public and that the 1 umber of visitors to Hampi Ruins will increase each year.

PLATE I (a)




Large Dolmen at Kalyandrug, Anantapur district.

PLATE 1 (b)




Hero-shrine at Kalyandrug, Anantapur district.

PLATE II (a)



Hero-shrine near Mudigallu, Anantapur district.

PLATE II (b)



Hero-shrine at Rayadrug, Bellary district.

PLATE III (a)




Dolmen Siva temples at Kambaduru, Anantapur district.

PLATE III (b)



Large Dolmen Siva temple at Kambaduru, Anantapur district.


PLATE IV (a)



Plan of a Dolmen at Kambaduru, Anantapur district.



PLATE IV (b)



Plan of an old Siva temple at Kambaduru, Anantapur district.

PLATE V (a)




Narasimha temple at Peddamudiyam, Cuddapah district.


PLATE V (b)



Siva temple at Penukonda, Anantapur district.



The Great Shambu-Nāth Stūpa near Katmandu in Nepal.




Stone model of a votive stupa from Gandhāra.



Parvāti temple at Kambaduru, Anantapur district.

PLATE VIII




 ${oldsymbol{J}}$

Plan of a Parvati shrine at Kambaduru, Anantapur district.

PLATE IX (a)

The stūpi over the Bakthavatsalar temple at Shermadevi, Tinnevelly district.



The stupi over the Chintalaraya temple at Tadpatri, Anantapur district.

Stone chakram found near the Kunti temple, Mahendragiri.



Bhima's temple, Mahendragiri.

PLATE XI (a)




The Yudhisthira temple, Mahendragiri.

PLATE XI (b)



View from Mahendragiri (Facing North).



Plan of Yudhisthira temple, Mahendragiri.

SECTION ON LINE A.B.


Scale of 5 10 15 20 Feet.

Section of Yudhisthira temple, Mahendragiri.

PLATE XIV (b)




Kunti temple, detail



Kunti temple, detail of doorway, Mahendragiri.

PLATE XV




PLAN

Scale of 5 0 10 Feet.


Plan of Kunti temple, Mahendragiri.

PLATE XVI (a)




The Nayak's Durbar Hall, Tanjore Palace. (Before Repairs.)

PLATE XVI (b)




The Nayak's Durbar Hall, Tanjore Palace. (After Repairs.)

PLATE XVII (a)



East Gateway of the Pattabi Rama Temple, Vijayanagar, Bellary District. (Before repairs.)

PLATE XVII (b)



East Gateway of the Pattabi Rama Temple, Vijayanagar, Bellary District. (After repairs.)

GOVERNMENT OF MADRAS

HOME DEPARTMENT

(Miscellaneous)

READ—the following paper:

Letter-from A. H. Longhurst, Esq., Superintendent, Archæological Survey, Southern Circle, Madras.

To—the Secretary to Government, Public Department. Dated—(Camp) Kotagiri, the 15th July 1916.

I have the honour to submit herewith in duplicate the annual progress report of this department for the year 1915-16.

- 2. The two sets of photographs taken during the year are submitted separately.
- 3. The reports on the condition of ancient monuments as far as they are received from the Superintending Engineers of I to VII Circles are submitted separately in type-written copy. The Superintending Engineer, VII Circle, states that further reports on certain ancient monuments in his circle are awaited and they will be submitted to Government as soon as they are received.

Order-No. 109, Home (Miscellaneous), dated the 5th September 1916.

Recorded.

- 2. The report is on the whole an improvement of its predecessor and the account given of the conservation work carried out during the year is less inadequate. conservation notes would, however, have been more useful if the Superintendent had given a concise and intelligible account of the more important works of repair done during the year and had omitted irrelevant matter copied from district gazetteers.
- 3. The expenditure on conservation was less than in either of the two previous years, and though the amount which was allowed to lapse was smaller, it was still excessive, being equal to 15 per cent of the budget allotment. The Superintendent should endeavour to see that the budget allotment is fully expended within the year.
- 4. Only six drawings were prepared during the year. The Government are inclined to think that the Superintendent might with advantage devote his time to the preparation of monographs on the chief architectural works in Southern India rather than to the production of essays on archæological problems such as that which is included in Part II of this report and its predecessor.
- 5. Copies of the report and of the photographs referred to in Appendix A will be forwarded to the Right Honourable the Secretary of State for India.

(True Extract)

P. RAJAGOPALA ACHARIYAR, Secretary to Government.

To the Superintendent, Archæological Survey, Madras., the Assistant Archæological Superintendent for Epigrophy., the Superintendent, Government Museum., the do. do. Press. ,, the do. do. Press.
,, all Collectors.
,, the Public Works Department.
,, the Government of India, Department of Education (with C.L.).
,, the Chief Commissioner of Coorg (with C.L.).
,, the Director-General of Archæology (with C.L.).

Editors' Table.

